

## **Inspection Form**

Form WMSC-IR-1

Washington Metrorail Safety Commission

Inspection Date	YYYY/MM/DD	Report Number	20220203-WMATA-LBW-01					
	2022/02/02	Report Number	20220205-WIVIATA-LBW-01					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	ROCC	Contact Information						
Inspection Location	Carmen Turner Training Facility 3500 Pennsy Dr, Hyattsville, MD 20785							

## **Inspection Summary**

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required <sup>1</sup>	No
Recommended Reinspection	No

## **Activity Summaries**

Inspection Activity #	1	Ins	spection Sub	ject	Power De	er Desk Demonstration				Activity Code					
Job Briefing Employee Name/Title	Manager Te Maintenace		Accompanied Inspector?			No	Out Brief Conducted	Time			12:00 PM		Outside Shift	No	
Related Reports	NA		Related CAPS / Findings			C-0037 - (Finding) Third rail power restoration is routinely rushed by ROCC management with a focus on restoring train service rather than a focus on following safety procedures									
Related Rules,	Ref		Rule	e or SOP			Standard		Other / Title				Checklist Reference		
SOPs, Standards, or Other	NA en			P #2 - Third rail power ergization and de- ergization procedures.		NA		NA				NA			
Inspection Location	Main Track	Yard	Station	осс	RTA Fa	acility	WMSC Office	Track Type	At-grade		Tunne	innel Ele		ated N/A	
				Х	X	(								Χ	
Line(s) & Track Number	Carmen Turner Training Facility 3500 Pennsy Dr, Hyattsville, MD 20785  Chain Marker and/o			or Station(s)	From NA				To NA						
	Head Car Number			lumber of Cars											
Vehicles	NA			NA Equipmen			ent	NA							
Description	The WMSC i		Number of Defects					0							
				he interaction	Recommended Finding?				No						
	in the restoration process between the newly established power desk, the roadway maintenance personnel, rail operations control center and the power desk assistant									Remedial Action Required?				No	כ
	superintendent. A copy of SOP #2 was provided to all in attendance along with a console work map for the planned demonstration. Several concerns were identified during the demonstration and feedback was provided to Metrorail personnel.									Recommended Reinspection?				No	)
Remedial Action															

<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Actionic closebut of hemedian Actions may also be subject to originity winds verification inspections to ensure confections are sufficient and effective.						
Inspector in Charge's Signature		Date 2022/02/02				
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team Richard David Natalie Quiroz					