

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Δσοηςν	/Denar	tmont	Information
Agency	/ Debar	ımenı	miormation

Inspection Date	YYYY/MM/DD	Report Number	20220802-WMATA-KEK-47		
inspection Date	2022/02/08	Report Number			
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name		
Rail Agency Department	WMATA	Contact Information			
Inspection Location	B04 Rhode Island ATCM Field Office	•			

Inspection Summary

Inspection Activity #	2
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	1
Recommended Finding	No
Remedial Action Required ¹	Yes
Recommended Reinspection	No

Activity Summaries

Activity Summaries																
Inspection Activity #	1	1	Inspection	on Subject ATCS, PMI, Shunt V			Verification T	Activity Code								
Job Briefing Employee Name/Title	Line Superi	rintendent Accompan			nied Inspector?		Yes	Out Brief Conducted	Yes	Yes Time		10:00 AM		Outside Shift	No	
Related Reports	N/A			_	Related CA	PS / Finding	gs									
Related Rules,	Ref			Rule c	or SOP			Standard		Other / Title			Checklist Reference			
SOPs, Standards, or Other	ATC 1000 Re	v 4.0						WMATA AS Records	P ATCM (MCP)				1012A-1 / 1012B-1			
Inspection Location	Main Track	Yard	Stat	ion	occ	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunnel		el Elevat		ted	N/A	
						Х	Х							Х		
Line(s) & Track	B04 Rhode	Island AI	TCM Field	Offic	۰.	Chain Ma	Marker and/or Station(s)			From T				o		
Number	DOT MIOUE	1314114 711	- CIVI I ICIG	Offic		Chairina	ricer uniu,	01 31411011(3)	CM: 154 + 69 CM: 182 + 68							
	Head Car	Number	r	Nu	mber of C	ars			Test jumpers, Shunt Straps (hard and soft), Digital Multi-Meter				,	,		
Vehicles	N/	/A			N/A		Equipm	ent			n isolated inputs: with frequency read-out function, AF- le Extender PCB (US&S part no, N398028), Alstom-GRS					
	ATCS, PMI, S	Shunt Verification Test and Wayside Inspection. Performed jointly. Number of Defects								2						
Description										Recommended Finding?					N	No
Description										Remedial Action Required?					Y	Yes
	Recommended Reinspec							spection?				No				
Remedial Action	(1) MOC must follow-up with mitigation of missing Third Rail Cover in accordance with WMATA procedures for corrective maintenance. (2) The newly installed Compliance Officer is now in place and data sheets are to be signed off going forward to comply with WMATA PMIs.															

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, do	data, or other evidence) to close out the Remedial
Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.	

retion: closeout of nemedial retions may also be subject to origining withse verification inspections to crisare corrections are sufficient and effective.					
Inspector in Charge's Signature		Date 2022/02/08			
Inspector in Charge's Name Kemmery Kendrick	Inspection Team				