

Washington Metrorail Safety Commission

Agency/Department Information

	YYYY/MM/DD	Provide Alexandree	20220240 1444474 1014/04						
Inspection Date	2022/02/10	Report Number	20220210-WMATA-LBW-01						
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name						
Rail Agency Department	Roadway Worker Protection	Contact Information							
Inspection Location	Archives Station (F02) to L'Enfant Plaza Station (F03) track walk								
Inspection Summary	Inspection Summary								
Inspection Activity #		1							
Activity Code									
Inspection Units									
Inspection Subunits									
Defects (Number)		5							
Recommended Finding		No							
Remedial Action Required ¹		No							

Yes

Recommended Reinspection

Activity Summaries

Inspection Activity #		Insp	ection Sub	ect					Activity Code						
Job Briefing Employee Name/Title	S. Fennel - C Preparednes		nergency	Accompan	ied Inspecto	or?	Yes	Out Brief Conducted	Yes	Yes Time			AM	Outside Shift	Yes
Related Reports	20220202-W	MATA-LBW-	-01	Related CAPS / Findings				NA							
	Ref		Rule	or SOP			Standard		Other /	Title			Check	ist Refere	ence
Related Rules, SOPs, Standards, or Other	NA a P o			ISRPH Chapter 5 -Roadway /orker Protection SOP 28 - rotection for Roadway Workers nd Establishment of Third Rail ower Outages and Work Areas n the Roadway 28.5.2.4, 28.5.3.1, 8.5.3.7 and Appendix A			NA		NA				NA		
Inspection Location	Main Track	Yard	Station	OCC	RTA F	acility	WMSC Office	Track Type	At-g	At-grade Tunnel		el	Eleva	ted I	N/A
	Х										Х				
Line(s) & Track Number	Archives Sta Station (F03	. ,		Plaza	Chain Ma	irker and/o	or Station(s)	Archives Statio	From L'Ent				To Ifant Plaza Station		
Vahialaa	Head Car	Number	N	umber of (Cars	E automa		NA							
Vehicles	N	A		NA	Equipment NA										
								training track	Number of Defects				5		
	walk. The training exercise was attended by 10 District of Columbia emergency responders, 2 WMSC inspectors and 4 Washington Metropolitan Area Transit Authorit								Recommended Finding?					No	
	Remedial Action Required? (WMATA) personnel. Prior to the training walk a Roadway Worker Job Safety Briefing (RJSB) was conducted by roadway worker in charge (RWIC) OEP 28. The RJSB was complete, but the RWIC had the crew sign acknowledgment of the briefing before receiving it. This does not align with MSRPH 5.5 (RSJB). Before entering the roadway, the RWIC verified the personal protective equipment (PPE) of all personnel entering the roadway. The form of protection for this training walk was Advance Mobile Flagger (AMF) with a Watchman Lookout (W/L). Third rail power would be energized during this Emergency First Responder training inspection. OEP 30 was the AMF located at L'Enfant Plaza Station and OEP 26 performed the duties of the W/L. After conformation was received from OEP 30, the training inspection team entered the roadway on track 1 Archives - Navy Memorial Station in the direction of L'Enfant Plaza Station. All trains passing the training crew were observed following AMF procedures. Four fire extinguishers (FE) were past due for inspection with two having two having no inspection tag and the activation pin pulled. A non-illuminated light was observed above an emergency exit door. Several third rail cover board were missing, and trash and debris was observed on the safety walk. Upon arrival at L'Enfant Plaza station a debriefing was conducted with the RWIC.								Remedial Action Required?				No	0	
Description									Yes						
Remedial Action															



Washington Metrorail Safety Commission

Photos:

RJSB_without_Name.jpg

	10	and the second
- alut	WHERE BOADSAR ON LANSIN SAME IN THE	
and the second s		
States without states of the local division of the local divisiono	and CEP 74	
	IPPING HARPING	
the set a cel	THE S	
themes and hanness - Salara	WALL THE THE PART - 7 A	C . ET
The state of the s		
NAME AND POST OFFICE ADDRESS OF TAXABLE POST OFFICE ADDRESS OFFICADOFFICADOFFICE		
Annual Annual Annual	E3	
COLUMN TRACE		
Management and an other states of the second states	- 22 - 17	215
And and a second second second second	20 00 00 000 000 000 000 000 000 00	
		_
		_
		_
		-
		-
		-
		-

FE_no_Tag_1.jpg



Form WMSC-IR-1



Form WMSC-IR-1

FE_no_tag_2.jpg




FE_not_inspected.jpg





Form WMSC-IR-1



Missing_cover_board.jpg





Form WMSC-IR-1

Trash.jpg



¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

 Inspector in Charge's Signature
 Date

 2022/02/10
 2022/02/10

		2022/02/20
Inspector in Charge's Name	Inspection Team	
LeBon Bruce Walker	Richard David	