

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Increation Date	YYYY/MM/DD	Report Number	20220218-WMATA-LBW-01					
Inspection Date	2022/02/18	Report Number	20220216-WWATA-LBW-01					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	Rail Transportation	Contact Information						
Inspection Location	lexanderia Rail Yard 3201 Eisenhower Ave. Alexandria, VA							

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	5
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Insp	ection Subj	Alexanderia Yard Service & Inspection (S&I) Facility			Activity Code									
Job Briefing Employee Name/Title	Lewis Taper - S&I Supervisor Tom Clark - Acting Superintendent			Accompanied Inspector?			Yes	Out Brief Conducted	Yes	Yes Time 10			10:00 AM Out		No	
Related Reports	NA			Related CAPS / Findings NA			NA	•	•		-	•				
Related Rules,	Ref Ru			ule or SOP Standard				Other / Title					Checklist Reference			
SOPs, Standards, or Other	NA		NA	A NA			NA	NA			NA					
Inspection Location	Main Track	Yard	Station	occ	RTA Fa	cility	WMSC Office	Track Type	At-grade		Tunnel		Eleva	ted	N/A	
					Х											
Line(s) & Track		exanderia Rail Yard 3201 Eisenhower Chain Marker and/or Station(s)					From				То					
Number	Ave. Alexand	Iria, VA	-					NA	N/				4			
Vehicles	Head Car	Number	N	umber of C	ars	Equipm	ent	NA								
	NA.		<u> </u>	NA												
								dria Rail Yard	Number o					5		
	observed in the performance of their jobs, safety equipment was inspected, and the							Recommended Finding?						No		
								nce - 12 fire	Remedial Action Required?					No	0	
Description	extinguishers in compliance and 1 Due for inspection - 3 eye wash stations - blue flag protection was being utilized - rail vehicles on lifts were chocked - chemical spill kits in use - Metrorail personnel wearing all required personnel protective equipment (PPE) An exit briefing was conducted with the S&I Acting Superintendent discussing all defects identified during this inspection and an email was sent to Metrorail management. The defects identified during this inspection were: 1. Two entry doors for lower-level high voltage rooms of the S&I Shop, B-9 AC Switchboard Battery Room and B-1 High Voltage Room doors could be closed but they could not be locked. These room are restricted entry only to protect workers "Personnel Shall Not Enter Without Receiving Permission from MOC" 2. One additional high voltage room was open and accessible but was secured during the inspection. 3. Aerosol Only hazardous material storage locker was storing non aerosol liquid. 4. The area labeled as area labeled as "Hot Works Area" does not have a fire extinguisher.									s						
Remedial Action														•		



Photos:

eye_wash_station.jpg



Hot_Wash_Area.jpg







Unsecured_door_2.jpg








Washington Metrorail Safety Commission

Form WMSC-IR-1





¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to analyze the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Actions.

Inspector in Charge's Signature	be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.	Date 2022/02/18
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team Manuel Lopez John Renzo Tiffany Minor	