

**Inspection Form** 

## Washington Metrorail Safety Commission

## Agency/Department Information

Inspection Date		YYYY/MM/DD	Report Number	20220303-WMSC-RRD-1				
Inspection Date		2022/03/09	Report Number					
Rail Agency Name	Wash	nington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	SAFE		Contact Information					
Inspection Location	Carn	nen Tuner Facility 3500 Pennsy Drive Landover Md 20785						
Inspection Summary								
Inspection Activity #			1					
Activity Code								
Inspection Units								
Inspection Subunits								
Defects (Number)		1						
Recommended Finding			No					
Remedial Action Required <sup>1</sup>								

Yes

## Recommended Reinspection Activity Summaries

Inspection Activity #	1	Ins	pection Subj	ect	ROCC	ROCC				Activity Code					
Job Briefing Employee Name/Title	N/A			Accompanied Inspector?		No	Out Brief Conducted	No	Time		10:3	80 AM	Outside Shift	No	
Related Reports	Previous ROOC inspection reports Reports related to dysfunction in the ROCC			Related CAPS / Findings WM			WMSC C0037 W	WMSC C0037 WMSC C0020							
	Ps, Standards, Management Officer			or SOP			Standard		Other / Title				Checklist Reference		
Related Rules, SOPs, Standards, or Other				50P 1A SOP 2					NIMS ICS						
Inspection Location	Main Track	Yard	Station	OCC	RTA F	acility	WMSC Office	Track Type	At-grade Tunn		nel Elevat		vated N/A		
				х											
Line(s) & Track	Carmen Tun	,	3500 Penns	y Drive	Chain Ma	rker and/	or Station(s)		From	From			То		
Number	Landover Mo	a 20785	_					N/A				N/A			
Vehicles	Head Car Number			Number of Cars Equipm			cCTV Fire Liais		ison Workstation						
	N/	/Α		N/A											
Description	The WMSC inspector conduct an 2nd shift inspection of the ROCC Rail 1, Fire Liaison, and									Number of Defects					
	new MAC potion. General observation of the room was also observed. Covid 19 protocol was in place. Big board pertained the current information. Fire Life Safety assets were in									Recommended Finding?					C
	compliance. Fire Liaison training was taking place. Good mid shift turnover with									Remedial Action Required?					
	, pertinent in	formation.	J						Recommended Reinspection?					Ye	s
Remedial Action															

<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

 Inspector in Charge's Signature

hispector in charge's signature		2022/03/09
Inspector in Charge's Name	Inspection Team	
Richard David		