

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

811								
Inspection Date	YYYY/MM/DD	Report Number	20220324-WMATA-LBW-02					
	2022/03/24	Report Number	20220324-WIVIATA-LBW-02					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	RTRA	Contact Information						
Inspection Location	Rhode Island Ave to Gallery Place - China Town							

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity					Train and	votor n	aninlina ana	ration							
#	1	Insp	Inspection Subject Train operator inspection				iainine ope	Activity Code							
Job Briefing Employee Name/Title	NA			Accompanied Inspector?			No	Out Brief Conducted	No	Time		07:05 AM		Outside Shift	Yes
Related Reports	NA		Related CAPS / Findings NA			NA									
Related Rules,	Ref		e or SOP			Standard		Other / Title				Checklist Reference			
SOPs, Standards, or Other	NA Bas			P #40 Door operations SOP #50 seline Announcements GR '9; 3.82		NA		NA				NA			
Inspection Location	Main Track	Yard	Station	OCC	RTA F	acility	WMSC Office Track Type		At-grade Tunne		el Elevate		ted	N/A	
	Х		Х						X X						
Line(s) & Track	Rhode Islan	d Ave to G	allery Plac	ce - China					From				То		
Number	Town	u Ave to G	Chain Marker and/o			or Station(s)	Rhode Island	Avenue Station Gallo				ery Place - China Town ion			
Vehicles	Head Car Number N			Number of Cars			o m t	AN							
venicies	6004			NA Equipme			ent	AN							
	The WMSC inspector conducted a riding inspection of Train ID 101 from Rhode Island								Number of Defects						0
	Avenue Station to Gallery Place. The purpose of the inspection was train operator (TO) rules compliance. On approach to Rhode Island Avenue Station, the TO entered and								Recommended Finding?						No
Description	properly berthed at the 8-car marker. The TO was observed following all rules of SOP #4								Remedial Action Required?						No
	(door operations). The TO was observed entering all stations at under 39mph and responded correctly to all over speed alarm conditions. The train operator performed all required train announcements.								Recommended Reinspection?					No	
Remedial Action															

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/03/24
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team	