

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

- 0								
Inspection Date	YYYY/MM/DD	Report Number	20220531-WMATA-RRD-2					
	2022/06/17	Report Number	20220331-WIVIATA-NND-2					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	SAFE	Contact Information						
Inspection Location	Carmen Turner Facility 3500 Pennsy Dr. Landover MD. 20785							

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	1
Recommended Finding	Yes
Remedial Action Required ¹	Yes
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Ins	pection Sub	ject	ROCC Fire Liaison/MAC observation			Activity Code								
Job Briefing Employee Name/Title	N/A			Accompanied Inspector?			No	Out Brief Conducted	No	Time			02:38 PM Outside Shift		No	
Related Reports	Previous ROCC reports and observations			Related CAPS / Findings					•	•		=				
	Ref Rul			e or SOP			Standard		Other / Title				Checklist Reference			
Related Rules, SOPs, Standards, or Other	Fire Life Safety/Emergency Management audit Agency Safety Plan Council Of Government Memorandum of Understanding.			OP 1A												
Inspection Location	Main Track	Yard	Station	occ	RTA Facility		WMSC Office	Track Type	At-grade Tunnel		el Eleva		ted I	N/A		
				Х											Χ	
Line(s) & Track Number		Turner Facility 3500 Pennsy Dr. Chain Marker and/or Station(s)				N/A	From T				0					
Number	Landover MD															
Vehicles	Head Car Number Of (N/A			Fauinment				tation FLS assets in the ROCC (extinguishers and AED in Big Board OEP training section.								
	The WMSC inspection conducted an unannounced inspection of the ROCC. The WMSC								Number of Defects 1							
Danielie.	workstation and the CCTV had no issues. ROCC cleaning and disinfectant was being performed. The new 7K rail Car for training was not acquired for training and the tunnel									Recommended Finding?					Yes	
Description	was in the process of some additional cleaning before the cars were installed.								Remedial Action Required?				Yes			
								Recommended Reinspection?					Yes			
Remedial Action	Repair the big board															

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature	Date 2022/06/17		
Inspector in Charge's Name Richard David	Inspection Team N/A		