

Inspection Form

Washington Metrorail Safety Commission

Agency/Department Information

		YYYY/MM/DD	Description of the second					
Inspection Date		2022/07/13	Report Number	20220602-WMATA-RRD-1				
Rail Agency Name	Was	nington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	SAF	E	Contact Information					
Inspection Location	New	New Carrollton Rail Yard 4700 Garden City Dr. New Carrollton MD. 20784						
Inspection Summary								
Inspection Activity #			1					
Activity Code								
Inspection Units								
Inspection Subunits								
Defects (Number)		2						
Recommended Finding		No						
Remedial Action Required ¹			Yes					

Yes

Recommended Reinspection

Remedial Action Required¹

Activity Summaries

Inspection Activity #	1 Inspection Sub		ect	ct 7 K back to back training				Activity							
Job Briefing Employee Name/Title				Accompanied Inspector?		or?	No	Out Brief Conducted	No	Time		11:45 AM		Outside Shift	No
Related Reports				Related CAPS / Findings											
	Ref Ru			ule or SOP			Standard		Other / Title				Checklist Reference		
Related Rules, SOPs, Standards, or Other	7K Series Rail Car wheel Back to Back Journal Bearing Measurement Inspections Version 4.12. 7K return to service plan.														
Inspection Location	Main Track	Yard	Station	OCC	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunne		el Elevated		ted N	N/A	
		Х													Х
Line(s) & Track Number	New Carrollton Rail Yard 4700 Ga Dr. New Carrollton MD. 20784			iarden City Chain Marker and/o			or Station(s)	From N/A			To N/A				
	Head Car	Number	N	umber of C	Cars										
Vehicles	N/A			N/A Equipmen			ent	PPE Digital Inc	dicator Ga	uge					
Description	The WMSC inspector conducted an unannounced inspection of the 7K Rail Car Back to									Number of Defects				2	
	Back training conducted at New Carrollton Rail Yard facility. Training was delayed due to no one in attendance. 1 student arrived and a safety briefing was given prior to the									Recommended Finding?				No	J
	commencement of training. Training ended due to a malfunctioning Digital Indicator									Remedial Action Required?				Yes	5
	Gauge and insufficient class numbers. Adequate material was available, there was a good classroom setting and a very good description of what was expected/goal of the training.									ecommended Reinspection?			Yes	Yes	
Remedial Action	Maintain an adequate level of instruction, class ratio, roster and working equipment to satisfy the requirements for the Back to Back 7K rail car testing and return to service plan for the 7K rail cars.														

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/07/13
Inspector in Charge's Name Richard David	Inspection Team N/A	