



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

| | | | |
|-------------------------------|---|-------------------------------|---------------------|
| Inspection Date | YYYY/MM/DD 2022/07/28 | Report Number | 20220725-WMSC-RRD-1 |
| Rail Agency Name | Washington Metropolitan Area Transit Authority | Rail Agency Department | Name |
| Rail Agency Department | SAFE/OEP | Contact Information | Nickea Bradley |
| Inspection Location | Branch Ave Station 4704 Old Soper Rd. Suitland MD 20746 | | |

Inspection Summary

| | |
|---|-----|
| Inspection Activity # | 1 |
| Activity Code | |
| Inspection Units | |
| Inspection Subunits | |
| Defects (Number) | 0 |
| Recommended Finding | No |
| Remedial Action Required¹ | No |
| Recommended Reinspection | Yes |

Activity Summaries

| | | | | | | | | | | | |
|---|---|-------------------------------|--------------------------------|----------------------------|---------------------------------------|--------------------|-------------------------|----------------------------------|-------------------------|----------------------------|------------|
| Inspection Activity # | 1 | Inspection Subject | Branch Ave Station | | | | Activity Code | | | | |
| Job Briefing Employee Name/Title | No | Accompanied Inspector? | | Out Brief Conducted | | Time | | Outside Shift | No | | |
| Related Reports | Industry Safe 4580 | | Related CAPS / Findings | | | | | | | | |
| Related Rules, SOPs, Standards, or Other | Ref | Rule or SOP | | | Standard | | Other / Title | | | Checklist Reference | |
| | WMATA's Design Criteria for stations Section 3.7 3.7.1 Station Platform and Train room Items. American Disabilities Act. | | | | | | | | | | |
| Inspection Location | Main Track | Yard | Station | OCC | RTA Facility | WMSC Office | Track Type | At-grade | Tunnel | Elevated | N/A |
| | | | X | | | | | X | | | |
| Line(s) & Track Number | Branch Ave Station 4704 Old Soper Rd. Suitland MD 20746 | | | | Chain Marker and/or Station(s) | | From | | To | | |
| | | | | | | | Station Platform Limits | | Station Platform Limits | | |
| Vehicles | Head Car Number | | Number of Cars | | Equipment | | N/A | | | | |
| | N/A | | N/A | | | | | | | | |
| Description | The WMSC inspector conducted a unaccompanied follow-up inspection from Industry Safe report 4580 which describes ADA tile on the platform to be in unsatisfactory condition which lead to a safety concern. Contact was made to SAFE's Prevention and Mitigation Group who directed the issue to the correct division and corrected the deficiency. | | | | | | | Number of Defects | | 0 | |
| | | | | | | | | Recommended Finding? | | No | |
| | | | | | | | | Remedial Action Required? | | No | |
| | | | | | | | | Recommended Reinspection? | | Yes | |
| Remedial Action | | | | | | | | | | | |

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

| | |
|--|-------------------------------|
| Inspector in Charge's Signature | Date 2022/07/28 |
| Inspector in Charge's Name Richard David | Inspection Team N/A |