

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Report Number	202201009-WMATA-DLB-1						
	2022/10/14	Report Number	202201009-WMATA-DLB-1						
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name						
Rail Agency Department	RTRA	Contact Information							
Inspection Location	Silver Line Phase II Extension Wiehle Reston East to Ashburn								

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity #	1	Ins	pection Subj	Operator Training/Silver Line Phase II Extension Familiarization Inspection.				Activity (
Job Briefing Employee Name/Title	Acting Direc	tor ROQT		Accompanied Inspector?				Out Brief Conducted	Yes Time 09:			09:00 A	00 AM Outside Shift		No	
Related Reports				Related CAPS / Findings					· ·	3		-			•	
Related Rules.	Ref		Rule	le or SOP			Standard		Other /	Other / Title				Checklist Reference		
SOPs, Standards, or Other																
Inspection Location	Main Track	Yard	Station	осс	RTA F	acility	WMSC Office Track Type		At-grade Tunne		el Eleva		ted N/A			
	Х															
Line(s) & Track Number	Silver Line F Reston East			ehle Chain Marker and/			or Station(s)	From Wiehle Reston East				To Ashburn				
Vehicles	Head Car	Number	Nı	umber of C	Cars	Equipm	ent									
							n Inspection.		Number o	f Defects				0		
	implemente to the Silver				Recommended Finding?					No						
	The Training			Remedial Action Required?					No)						
Description	Three WMSC inspectors conducted a pre-revenue inspection of the train operator familiarization training and simulated rail service. The familiarization training began at the Wiehle-Reston East Station and traversed the six new stations and ended at the Ashburn Station. The training included the High rail-vehicle storage area, the diamond and universal interlockings, the signals for entering and exiting the Dulles rail yard and the Dulles Airport runway protection zone. The WMATA Instructors rode in the train operators cab with the rail vehicle operator as they traveled the silver line extension answering relevant questions. After completing their trip and servicing stations from Downtown Largo to Wiehle-Reston East Station, the train was taken out of service and cleared of customers. The training then shifted to simulated service requiring the train operator to make all required stops and service all six new stations. WMSC The train reversed ends and traveled back to resume its normal service once reaching Wiehle Reston East Station. The training provided a practical exposure to the new silver line extension and allowed the train operators to become familiar while asking questions of the rail instructors.								No)						

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Action: closedat of hemedian retions may also be subject to origining winde verification inspections to choure corrections are sufficient and effective.						
Inspector in Charge's Signature		Date				
		2022/10/14				
Inspector in Charge's Name	Inspection Team	!				
Darrell Braxton	Bruce Walker Richard David					