

**Inspection Form** 

# Washington Metrorail Safety Commission

#### Agency/Department Information

Inspection Date	YYYY/MM/DD	Report Number	20230117-WMSC-LBW-1					
Inspection Date	2023/01/30	Report Number	20250117-WWSC-LBW-1					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	ATC	Contact Information						
Inspection Location	Inspection Location Brookland - Catholic University Station 801 Michigan Ave NE, Washington, DC 20017							
Inspection Summary								
Inspection Activity #		1						
Activity Code	y Code SAFE-PI-QAI							
Inspection Units	1							
Inspection Subunits	0							
Defects (Number)	0							

No No

No

#### Remedial Action Required<sup>1</sup> Recommended Reinspection

Recommended Finding

## Activity Summaries

Inspection Activity #	1	Insp	ection Sub	ject	ATC Verification Inspection		Activity Code			SAFE-PI-QAI					
Job Briefing Employee Name/Title	NA			Accompanied Inspector?		r?	No	Out Brief Conducted	No	Time		10:00 AM		Outside Shift	Yes
Related Reports	ATC audit report			Related CAPS / Findings NA			NA								
Related Rules,	Ref Ru			Rule or SOP S			Standard		Other / Title				Checklist Reference		
SOPs, Standards, or Other		NA	NA			NA			NA			NA			
Inspection Location	Main Track	Yard	Station	OCC	RTA Fa	cility	WMSC Office	Track Type	At-g	At-grade Tunne		el Elevato		ited	N/A
			х												
Line(s) & Track	Brookland -	Brookland - Catholic University Station 801 Chain Marker and/or Station(s)					From					То			
Number	Michigan Av	ve NE, Wash	ington, DO	b, DC 20017 Chain Warker and/or Station(s) B05 Station Pla		atform B05 St				Station Platform					
Vehicles	Head Car Number			Number of Cars			ent NA								
	NA			NA Equipmer											
	The WMSC received documentation of an ATC inspection completed in Room 208 at the							Number of Defects				0			
Description	Brookland (B05) station. Room 208 according to documentation is an ATC Field Office. The inspection concluded that Room 208 is indeed a Field office and not a train control room. The Train Control Room was identified as room 210.								Recommended Finding?					No	
									Remedial Action Required?					No	
									Recommended Reinspection?				No		
Remedial Action															

Washington Metrorail Safety Commission



**Inspection Form** 

20230117\_100557.jpg





**Inspection Form** 

## Form WMSC-IR-1

# 20230117\_101313.jpg



 1 The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

 Inspector in Charge's Signature
 Date

		2023/01/30
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team NA	