

WMSC Commissioner Brief: W-0253 Evacuation for Life Safety Reasons – Wheaton Station – May 18, 2023

Prepared for Washington Metrorail Safety Commission meeting on January 23, 2024

Safety event summary:

On Thursday, May 18, 2023, Wheaton Station was evacuated due to a shooting inside the station. One person was killed in the shooting. Individuals believed to be related to the shooting subsequently entered the roadway. No one was injured during the evacuation for life safety reasons.

At 5:52 p.m., the Train Operator of Train 111 on track 1 contacted the Radio Rail Traffic Controller in the Rail Operations Control Center (ROCC) and reported hearing a loud noise as their train departed Wheaton Station toward Glenmont Station. A minute later, the Train Operator of Train 109 on track 2 (travelling toward Shady Grove Station) at Wheaton Station reported that a customer advised them that a person had been shot near the escalator, and that two men were seen running into the tunnel toward Forest Glen Station. At the same time, the Wheaton Station Manager reported to a Rail Operations Information Center (ROIC) Controller in the ROCC that a person had been shot. The Information Controller directed the Station Manager to go to a place of safety. Bystanders called Montgomery County 911 to request an emergency response.

The ROIC Controller notified the Metro Transit Police Department (MTPD) and the ROCC Operations Manager.

An MTPD Dispatcher dispatched MTPD officers to the station and the Operations Manager instructed the Radio Rail Traffic Controller to have the Train Operator of Train 109 to offload their train and perform a track inspection (with only the Train Operator on board) on track 2 to Forest Glen Station to check for unauthorized persons on the roadway.

At 5:59 p.m., train service was suspended between Silver Spring and Glenmont stations.

At approximately 6:03 p.m., the first MTPD Officer arrived on scene. At 6:04 p.m., a ROIC Controller instructed the Station Manager to evacuate the station.

Multiple track inspections were conducted between Wheaton and Glenmont stations on tracks 1 and 2 with nothing found.

At 7:27 p.m., trains were allowed to resume service toward Glenmont Station, bypassing Wheaton Station. Train service was then suspended again at 7:43 p.m. At 9:16 p.m., trains were allowed to begin single tracking, bypassing Wheaton Station, as the police investigation continued. The station remained closed until the next morning on Friday, May 19, 2023.

Probable Cause:

The probable cause of this evacuation for life safety reasons was a shooting in the station.



Washington Metropolitan Area Transit Authority Department of Safety (SAFE) Office of Safety Investigations (OSI)

FINAL REPORT OF INVESTIGATION E23337

Date of Event:	May 18, 2023
Type of Event:	Evacuation for Life Safety Reasons
Incident Time:	17:51 Hours
Location:	Wheaton Station – Escalator X01
Time and How received by SAFE:	17:55 Hours – SAFE/MAC
WMSC Notification Time:	18:51 Hours
Responding Safety Officers:	Office of Emergency Preparedness (OEP)
Rail Vehicle:	None
Injuries:	Fatal
Damage:	None
Emergency Responders:	Metro Transit Police Department (MTPD)
	Montgomery County Police Department (MCPD)
	Montgomery County Fire and Emergency Services
	(MCEMS)
SMS I/A Incident Number:	20230518#108595

Wheaton Station – Evacuation for Life Safety

May 18, 2023 Table of Contents

Abbreviations and Acronyms	3
Executive Summary	4
Incident Site	4
Field Sketch/Schematics	4
Purpose and Scope	5
Investigative Methods	
Investigation	5
Chronological ARS Timeline	7
Weather	10
Related Rules and Procedures	10
Human Factors	10
Evidence of Fatigue	10
Fatigue Risk	10
Post-Incident Toxicology Testing	10
Findings	10
Immediate Mitigation to Prevent Recurrence	10
Probable Cause Statement	10
Recommended Corrective Actions	10
Appendices	12
Appendix A – RTRA Rail Supervisor and Station Manager Reports	12
Appendix B – Office of Emergency Preparedness (OEP) Report	14
Appendix C – Root Cause Analysis	17

Abbreviations and Acronyms

ссти	Closed-Circuit Television
DVEU	Digital Video Evidence Unit
MAC	Mission Assurance Coordinator
MCPD	Montgomery County Police Department
MTPD	Metro Transit Police Department
MCFRS	Montgomery County Fire and Rescue Service
MSRPH	Metrorail Safety Rules and Procedures Handbook
NOAA	National Oceanic and Atmospheric Administration
OEP	Office of Emergency Preparedness
ΡΑ	Public Address
RTC	Rail Traffic Controller
ROCC	Rail Operations Control Center
ROIC	Rail Operations Information Center
RTRA	Office of Rail Transportation
SOP	Standard Operating Procedure
SMS	Safety Measurement System
SAFE	Department of Safety
SOCC	Security Operations Control Center
WMATA	Washington Metropolitan Area Transit Authority
WMSC	Washington Metrorail Safety Commission

Executive Summary

*Note that all times listed are approximate and may contain minor variations due to differences between systems of record. *

On May 18, 2023, at 17:52 hours, the Train Operator of Train ID 111 reported to the Rail Operations Control Center (ROCC) that they heard a loud noise before departing Wheaton Station, track 1. At 17:53 hours, the Train Operator of Train ID 109, located at Wheaton Station on track 2, reported that a customer advised them that a person was shot near the escalators and observed two males running into the tunnel toward Forest Glen Station. The Station Manager located at Wheaton Station contacted the Rail Operations Information Center (ROIC) to report that a person was shot and requested the Metro Transit Police Department (MTPD) and emergency services. The Radio RTC instructed Train ID 109 to offload their train.

ROIC notified MTPD and the Operations Manager (OM) of the event. MTPD dispatched units to Wheaton Station. Montgomery County Dispatch contacted MTPD, advised them of the report, and that the Montgomery County Police Department (MCPD) was en route.

The Radio RTC instructed trains to perform a track inspection on tracks 1 and 2 between Silver Spring Station and Glenmont Station accompanied by MTPD and MCPD on board the trains. Train service between Silver Spring Station and Glenmont Station was suspended.

MTPD arrived and established an Incident Command Post. Wheaton Station was evacuated. One person in the station was fatally wounded in this event. On May 19, 2023, at 00:06 hours, Wheaton Station was reopened for normal train service.

The probable cause of the Evacuation for Life Safety Reasons Event on May 18, 2023, at Wheaton Station, was a person discharging a firearm, which resulted in a customer receiving fatal injuries. There were no major findings related to the response and recovery from this event.

Incident Site

Wheaton Station – In the tunnel area between Escalator X01 and the platform.

Field Sketch/Schematics



The above depiction is not to scale.

Incident Date: 05/18/2023 Time: 17:51 hours Final Report – Evacuation for Life Safety Reasons E23337

Drafted By: SAFE 708 – 07/07/2023 Reviewed By: SAFE 707– 07/17/2023 Approved By: SAFE 71 – 07/17/2023

Purpose and Scope

The purpose of this accident investigation and candid self-evaluation is to collect and analyze available facts, determine the probable cause(s) of the incident, identify contributing factors, and make recommendations to prevent a recurrence.

Investigative Methods

Upon receiving notification of the Evacuation for Life Safety Reasons event at the Wheaton Station on May 18, 2023, SAFE dispatched a cross-functional team to assess the scene and conduct the subsequent investigation. SAFE team members worked with relevant WMATA subject matter experts to review the incident's facts and data.

The investigative methodologies included the following:

- Site assessment through video and document review.
- Informal Interviews Collected through conversations with individuals during the investigation to provide background and supporting information. Written statements were reviewed from personnel present during the event.
- Documentation Review A collection of relevant work history information and process documentation contained in Metro systems of record. These records include:
 - Metrorail Safety Rules and Procedures Handbook (MSRPH)
 - National Oceanic and Atmospheric Administration (NOAA)
 - MTPD Hot Wash Summary
 - Maximo Data
 - Departmental reports
 - Written Statements from employee witnesses
- System Data Recording Review A collection of information contained in Metro Data Recording Systems. This data includes:
 - Audio Recording System (ARS) playback
 - System Performance On-Time Summary
 - Closed-Circuit Television (CCTV)

Investigation

On May 18, 2023, at 17:51 hours, Closed-Circuit Television (CCTV) revealed that a group of people engaged in an altercation on escalator X01. After exiting the escalator, a person fell to the ground in the tunnel area near the platform at Wheaton Station.

The Audio Recording System (ARS) revealed that at 17:52 hours, the Train Operator of Train ID 111 reported to ROCC that they heard a loud noise before departing Wheaton Station, track 1. At 17:53 hours, the Train Operator of Train ID 109 located at Wheaton Station on track 2 reported that a customer advised them that a person was shot near the escalators, and they saw two males running into the tunnel, in the direction of Forest Glen Station.

The Station Manager located at Wheaton Station contacted ROIC and reported a person was shot and requested MTPD to respond. The Radio RTC instructed Train ID 109 to offload their train.

ROIC notified MTPD and the OM of the event. At 17:54 hours, MTPD dispatched Units to Wheaton Station.

The Radio RTC instructed Train ID 133 to hold at Forest Glen Station, track 2.

Montgomery County Dispatch contacted MTPD and advised that they received a report of a shooting at Wheaton Station and that MCPD personnel were en route. At 17:55 hours, MCPD arrived at Wheaton Station.

At 17:56 hours, the Radio RTC, at the instruction of the OM, instructed Train ID 109 to offload the train due to the possibility that persons that entered the roadway were armed with handguns and to perform a track inspection to Forest Glen Station on track 2. At 17:58 hours, the Radio RTC instructed Train ID 133 to offload, reverse ends and perform a track inspection to Wheaton Station on track 1.

Montgomery County Fire and Rescue Services (MCFRS) responded to Wheaton Station.

At 17:59 hours, the Radio RTC announced that train service was suspended between Silver Spring Station and Glenmont Station.

At 18:00 hours, ROIC contacted the Bus Operations Control Center (BOCC) and requested a bus bridge between Silver Spring Station and Glenmont Station. The Radio RTC instructed Train ID 133 to continue the track inspection to Silver Spring Station on track 1.

At 18:03 hours, an MTPD Officer arrived at Wheaton Station. The Radio RTC instructed Train ID 109 to perform a track inspection to Forest Glen Station on track 2.

At 18:04 hours, MTPD established the Incident Command Post at Wheaton Station's kiosk. ROIC instructed the Station Manager to evacuate Wheaton Station. The Radio RTC granted an absolute block to Train ID 133 to continue the track inspection to Silver Spring Station on track 1. At 18:10 hours, Train ID 133 reported a good track inspection. At 18:17 hours, Train ID 109 reported a good track inspection.

At 18:21 hours, the Radio RTC instructed Train ID 113 to perform a track inspection between Silver Spring Station and Glenmont Station on track 1.

At 18:28 hours, MCFRS units departed Wheaton Station.

At 18:33 hours, an Office of Rail Transportation (RTRA) Supervisor arrived at Wheaton Station.

At 18:53 hours, the Radio RTC announced that train service was suspended between Forest Glen Station and Glenmont Station.

At 19:12 hours, Train ID 113 reported a good track inspection. At 19:18 hours, the Radio RTC instructed Train ID 113 to perform a track inspection between Glenmont Station and Wheaton Station on track 2. At 19:27 hours, Train ID 113 reported a good track inspection.

The Radio RTC announced that trains could continue in service to Glenmont Station, bypassing Wheaton Station. At 19:43 hours, the Radio RTC announced that train service was suspended again between Forest Glen Station and Glenmont Station.

At 20:12 hours, the On-Scene Commander announced that Command Post was terminated and MTPD personnel remained on the scene. At 21:02 hours, Montgomery County Crime Scene Investigators arrived on the scene.

At 21:16 hours, the Rail Supervisor located at Wheaton Station advised ROCC that trains could continue in service to Glenmont Station, single tracking on track 1, and bypassing Wheaton Station. At 21:18 hours, the Emergency Response Team (ERT) arrived on the scene.

At 22:33 hours, the Rail Supervisor located at Wheaton Station advised ROCC that trains could utilize tracks 1 and 2 to Glenmont Station, bypassing Wheaton Station.

At 22:36 hours, the Rail Supervisor located at Wheaton Station advised ROCC that MTPD turned the scene over to them.

At 23:00 hours, MTPD departed Wheaton Station.

At 23:12 hours, the Rail Supervisor located at Wheaton Station advised ROCC that the Office of Plant Maintenance (PLNT) was on the scene.

On May 19, 2023, at 00:06 hours, the Rail Supervisor located at Wheaton Station advised ROCC that all personnel were clear, and Wheaton Station could reopen. The Button RTC notified ROIC that Wheaton Station could reopen. At 00:07 hours, ROIC instructed the Station Manager to reopen Wheaton Station.

At 00:08 hours, Train ID 118 was the first train to service Wheaton Station on track 2. At 00:14 hours, MCPD departed Wheaton Station. At 00:21 hours, Train ID 120 was the first train to service Wheaton Station on track 1.

Chronological ARS Timeline

A review of ARS playback, i.e., phone and radio communications, revealed the following timeline:

Time	Description
	May 18, 2023
17:51:00 hours	A person was shot near the escalator at Wheaton Station. [MTPD DVEU]
17:52:19 hours	<u>Train ID 111</u> : Reported departing Wheaton Station and hearing a loud noise. <u>ROCC Radio RTC</u> : Inquired, "Did it sound like a gunshot?" <u>Train ID 111</u> : Responded, "I don't know." [Radio Ops 1]
17:53:14 hours	<u>Train ID 109</u> : Reported a customer advised that a person was shot near the escalator. <u>ROCC Radio RTC</u> : Acknowledged. <u>Train ID 111</u> : Reported customer observed two males running in the tunnel toward Forest Glen Station. [Radio Ops 1]
17:53:26 hours	<u>Station Manager</u> : Reported a person was shot and requested MTPD to respond. <u>ROIC Controller</u> : Acknowledged and advised to go to a place of safety. <u>Station Manager</u> : Responded, "Headed back to the kiosk." <u>ROIC Controller</u> : Acknowledged and instructed to stay in a place of safety. [Radio Ops 5]
17:53:39 hours	ROIC Controller: Notified MTPD of the event. [Phone SOCC 5D]

Time	Description		
17:53:47 hours	ROIC Controller: Notified the OM of the event. [Phone Rail 1]		
17:54:25 hours	MTPD Dispatch: Instructed Units to respond to Wheaton Station.		
	[MTPD 1X]		
17:54:34 hours	ROCC Radio RTC: Instructed Train ID 133 to hold at Forest Glen Station,		
	track 2.		
	Train ID 133: Acknowledged and repeated. [Radio Ops 1]		
17:54:39 hours	Button RTC: Notified the MTPD of the event. [Phone Ops 1]		
17:54:49 hours	Montgomery County Dispatch contacted MTPD and advised them of the event. [Phone SOCC 53]		
17:55:07 hours	MCPD arrived at Wheaton Station. [CCTV]		
17:56:32 hours	OM: Instructed to have Train ID 109 perform a track inspection.		
	[Ambient Fire Liaison]		
17:56:41 hours	ROCC Radio RTC: Instructed Train ID 109 to offload and perform a track		
	inspection to Forest Glen Station on track 2.		
	Train ID 109: Acknowledged and repeated. [Radio Ops 1]		
17:58:23 hours	ROCC Radio RTC: Instructed Train ID 133 to offload, reverse ends and		
	perform a track inspection to Wheaton Station on track 1.		
17 50 50 1	Train ID 133: Acknowledged and repeated. [Radio Ops 1]		
17:58:56 hours	MCFRS arrived at Wheaton Station. [CCTV]		
17:59:33 hours	ROCC Radio RTC: Announced train service suspended between Silver		
	Spring Station and Glenmont Station. [Radio Ops 1]		
18:00:44 hours	ROIC Controller: Contacted BOCC and requested a bus bridge between		
	Silver Spring Station and Glenmont Station.		
18:00:52 hours	[Phone ROIC Lead] <u>ROCC Radio RTC</u> : Instructed Train ID 133 to continue the track inspection		
10.00.52 10015	to Silver Spring Station on track 1.		
	<u>Train ID 133</u> : Acknowledged and repeated. [Radio Ops 1]		
18:03:03 hours	MTPD Unit: Reported they were at Wheaton Station. [MTPD 1X]		
18:03:28 hours	<u>ROCC Radio RTC</u> : Instructed Train ID 109 to perform a track inspection to		
10.00.20 110013	ROCC Radio RTC: Instructed Train ID 109 to perform a track inspection to Forest Glen Station on track 2.		
	Train ID 109: Acknowledged and repeated. [Radio Ops 1]		
18:04:38 hours	MTPD Unit: Advised the Incident Command Post was established at		
	Wheaton Station Kiosk. [MTPD 1X]		
18:04:48 hours	ROIC Controller: Instructed the Station Manager to evacuate Wheaton		
	Station. [Radio Ops 5]		
18:04:55 hours	ROCC Radio RTC: Granted an Absolute Block to Train ID 133 to continue		
	the track inspection to Silver Spring Station on track 1.		
	Train ID 133: Acknowledged and repeated. [Radio Ops 1]		
18:10:09 hours	Train ID 133: Reported a good track inspection.		
10.17.011	ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]		
18:17:01 hours	Train ID 109: Reported a good track inspection.		
	ROCC Radio RTC: Acknowledged and repeated. Instructed to continue a		
	track inspection on track 2.		
18:21:58 hours	<u>Train ID 109</u> : Acknowledged and repeated. [Radio Ops 1] <u>ROCC Radio RTC</u> : Instructed Train ID 113 to perform a track inspection		
10.21.30 HOUIS	between Silver Spring Station and Glenmont Station on track 1.		
	<u>Train ID 113</u> : Acknowledged and repeated. [Radio Ops 1]		
18:28:21 hours	MCFRS departed Wheaton Station. [CCTV]		

Incident Date: 05/18/2023 Time: 17:51 hours Final Report – Evacuation for Life Safety Reasons E23337

18:33:20 hours 18:53:58 hours 19:12:56 hours 19:18:02 hours 19:27:04 hours 19:27:32 hours 19:43:51 hours	Rail Supervisor: Advised on scene at Wheaton Station. ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Announced train service suspended between Forest Glen Station and Glenmont Station. [Radio Ops 1] Train ID 113: Reported a good track inspection. ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Instructed Train ID 113 to perform a track inspection between Glenmont Station and Wheaton Station on track 2. Train ID 113: Acknowledged and repeated. [Radio Ops 1] Train ID 113: Reported a good track inspection. ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] Main ID 113: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1] ROCC Radio RTC: Announced that trains continue in service to Glenmont Station, bypassing Wheaton Station. [Radio Ops 1]
19:12:56 hours 19:18:02 hours 19:27:04 hours 19:27:32 hours	ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Announced train service suspended between ForestGlen Station and Glenmont Station. [Radio Ops 1]Train ID 113: Reported a good track inspection.ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Instructed Train ID 113 to perform a track inspectionbetween Glenmont Station and Wheaton Station on track 2.Train ID 113: Acknowledged and repeated. [Radio Ops 1]Train ID 113: Reported a good track inspection.ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]Train ID 113: Reported a good track inspection.ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]Train ID 113: Reported a good track inspection.ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]
19:12:56 hours 19:18:02 hours 19:27:04 hours 19:27:32 hours	ROCC Radio RTC:Announced train service suspended between ForestGlen Station and Glenmont Station. [Radio Ops 1]Train ID 113:Reported a good track inspection.ROCC Radio RTC:Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC:Instructed Train ID 113 to perform a track inspectionbetween Glenmont Station and Wheaton Station on track 2.Train ID 113:Acknowledged and repeated. [Radio Ops 1]Train ID 113:Reported a good track inspection.ROCC Radio RTC:Acknowledged and repeated. [Radio Ops 1]Train ID 113:Reported a good track inspection.ROCC Radio RTC:Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC:Announced that trains continue in service to Glenmont
19:18:02 hours 19:27:04 hours 19:27:32 hours	Train ID 113: Reported a good track inspection.ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Instructed Train ID 113 to perform a track inspectionbetween Glenmont Station and Wheaton Station on track 2.Train ID 113: Acknowledged and repeated. [Radio Ops 1]Train ID 113: Reported a good track inspection.ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]Train ID 113: Reported a good track inspection.ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]
19:18:02 hours 19:27:04 hours 19:27:32 hours	ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Instructed Train ID 113 to perform a track inspectionbetween Glenmont Station and Wheaton Station on track 2.Train ID 113: Acknowledged and repeated. [Radio Ops 1]Train ID 113: Reported a good track inspection.ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]
19:27:04 hours 19:27:32 hours	ROCC Radio RTC:Instructed Train ID 113 to perform a track inspectionbetween Glenmont Station and Wheaton Station on track 2.Train ID 113:Acknowledged and repeated.[Radio Ops 1]Train ID 113:Reported a good track inspection.ROCC Radio RTC:Acknowledged and repeated.[Radio Ops 1]
19:27:04 hours 19:27:32 hours	between Glenmont Station and Wheaton Station on track 2. <u>Train ID 113</u> : Acknowledged and repeated. [Radio Ops 1] <u>Train ID 113</u> : Reported a good track inspection. <u>ROCC Radio RTC</u> : Acknowledged and repeated. [Radio Ops 1] <u>ROCC Radio RTC</u> : Announced that trains continue in service to Glenmont
19:27:32 hours	Train ID 113: Acknowledged and repeated. [Radio Ops 1]Train ID 113: Reported a good track inspection.ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]ROCC Radio RTC: Announced that trains continue in service to Glenmont
19:27:32 hours	<u>Train ID 113</u> : Reported a good track inspection. <u>ROCC Radio RTC</u> : Acknowledged and repeated. [Radio Ops 1] <u>ROCC Radio RTC</u> : Announced that trains continue in service to Glenmont
19:27:32 hours	<u>ROCC Radio RTC</u> : Acknowledged and repeated. [Radio Ops 1] <u>ROCC Radio RTC</u> : Announced that trains continue in service to Glenmont
	ROCC Radio RTC: Announced that trains continue in service to Glenmont
19:43:51 hours	Station, pypassing wheaton Station, Ikagio Ops 11
19:43:51 nours	
	<u>ROCC Radio RTC</u> : Announced train service suspended between Forest Glen Station and Glenmont Station. [Radio Ops 1]
20:12:01 hours	Incident Command Post: Announced Command Post was terminated and
20.12.01 110015	MTPD Units remained on the scene. [Radio MTPD 2X]
21:02:35 hours	Rail Supervisor: Advised Montgomery County Investigation on scene at
21.02.00 110013	Wheaton Station.
	ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]
21:16:42 hours	Rail Supervisor: Advised trains could single track to Glenmont Station on
	track 1 bypassing Wheaton Station.
	ROCC Radio RTC: Acknowledged and repeated. Announced for trains to
	continue in service to Glenmont Station single tracking on track 1, bypassing
	Wheaton Station. [Radio Ops 1]
21:18:54 hours	Rail Supervisor: Advised ERT was on scene at Wheaton Station.
	ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]
22:33:27 hours	Rail Supervisor: Advised trains could utilize tracks 1 and 2 to Glenmont
	Station, bypassing Wheaton Station.
	<u>ROCC Radio RTC</u> : Acknowledged and repeated. Announced that trains would continue in service to Glenmont Station on tracks 1 and 2, bypassing
	Wheaton Station. [Radio Ops 1]
22:36:53 hours	Rail Supervisor: Advised that MTPD turned the scene over to RTRA.
	<u>ROCC Radio RTC</u> : Acknowledged and repeated. [Radio Ops 1]
23:00:06 hours	MTPD departed Wheaton Station. [CCTV]
23:12:09 hours	Rail Supervisor: Advised PLNT Maintenance was on the scene.
	ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]
I	May 19, 2023
00:06:01 hours	Rail Supervisor: Advised all personnel were clear and Wheaton Station could
	reopen.
	ROCC Radio RTC: Acknowledged and repeated. [Radio Ops 1]
00:06:44 hours	Button RTC: Notified ROIC that Wheaton Station could reopen.
	[Phone Ops 1]
00:07:25 hours	ROIC Controller: Instructed the Station Manager to reopen Wheaton Station.
	Station Manager: Acknowledged. [Phone ROIC PA]
00:08:29 hours	Train ID 118 was the first train to service Wheaton Station on track 2. [Spots]
00:14:37 hours	MCPD departed Wheaton Station. [CCTV]
00:21:29 hours	Train ID 120 was the first train to service Wheaton Station on track 1. [Spots]

Incident Date: 05/18/2023 Time: 17:51 hours Final Report – Evacuation for Life Safety Reasons E23337

Drafted By: SAFE 708 – 07/07/2023 Reviewed By: SAFE 707 – 07/17/2023 Approved By: SAFE 71 – 07/17/2023

**Note: Times above may vary from other systems' timelines based on clock settings and reporting sources.

Weather

On May 18, 2023, at the time of the incident, NOAA recorded the temperature as 69°F, with clear skies, winds at 3 mph, and 80% humidity. The weather was not a contributing factor in this incident. (Weather source: NOAA – Location: Wheaton, MD)

Related Rules and Procedures

SOP #1A – Command, Control and Coordination of Emergencies on the Rail System Safety Bulletin: SB 23-02-D, Version: #1

Human Factors

Evidence of Fatigue

The biomathematical fatigue modeling application (SAFTE-FAST Web SFC) was not applied for this event.

Fatigue Risk

The biomathematical fatigue modeling application (SAFTE-FAST Web SFC) was not applied for this event.

Post-Incident Toxicology Testing

Post-Incident Toxicology Testing was not conducted for this event.

Findings

- A group was involved in an altercation on escalator X01 prior to the shooting.
- A customer reported observing two people enter the roadway on track 2.
- The injured person was transported to a local hospital.
- The event resulted in a fatality.
- Track inspections yielded negative findings for unauthorized persons in the roadway.

Immediate Mitigation to Prevent Recurrence

- Wheaton Station was evacuated.
- Joint track inspections were conducted with police personnel on tracks 1 and 2 between Silver Spring and Glenmont Stations with negative results.
- MCPD and MCFRS arrived to investigate and render aid.

Probable Cause Statement

The probable cause of the Evacuation for Life Safety Reasons Event on May 18, 2023, at Wheaton Station, was a person discharging a firearm, which resulted in a customer receiving fatal injuries. There were no major findings related to the response and recovery from this event.

Recommended Corrective Actions

Based on the events surrounding this fatality, there are no recommendations associated with this event. Review of the system records of data, did not identify significant findings related to the response and recovery from this event.

Appendices

THE REAL PROPERTY OF THE PARTY		be completed for		Page of	,
Date:	Incident Time:	Time Reported		Reported by: Customer	Employee 🗆
5/18/2023	6:05PM	6:051	M	ROCC Other O	
Location		a law	6/Dection Free	Chain Markey Parent P	
Station	Mezzanine 3	4 Irack	#/Destination	Chain Marker/Signal Num	ber
TYPE OF INCIDENT				1.1.11	A CONTRACTOR OF THE OWNER
Property Damage	Smoke	Ca Fir		Customer Complai	nt
Customer injury	Customer Ilin		nployee Injury	Employee Illness	
Criminal Activity WEATHER	Elevator Entra	GHT CONDITIONS	il Vehicle Incident (natural lighting		escription of incident)
Clear M Rain 🗆		wn/Dusk 🗅 Daylight		Lights On Light	
Snow 🗆 Sleet/Ice 🗆		rk 🗆 Tunnel/Undergro		Lights Not Workin	g 🗆 👘
STATION INCIDENTS	Always include	AFC #:	er you use for Mi	C/AFC/EOC Room Number/Location:	
clevalo//Escalator#	A	N	A	Noom Number/Location:	Mean ino.
Failure Number(s):	- 11		~		- aggaine
Λ	14				
Parking Lot D Paid Area			nce 🗆 Stairway #	Platform I Anci	lary Room 🗳
Injury/Illness reported abo Name of Responding Supe			ent of PLNT/AFC or	other WMATA responder	
NIA		and the company	NA		
TRAIN INCIDENTS					
Train ID	Destination	Car Numbers(I	ist all cars in consist): Lead Ca	ACIA
Name of Responding Supe	rvisor /	Name	Department of CMN	T/TRST or other WMATA n	IV/71
anne e mayonany cope	NIA		N	/A	- approved and a
DESCRIBE THE INCID	ENT: Include wh	at you did to corre	ect the problem a	ind who you notified a	ind when.
Describe any pro	perty damage and th	e extent of any injuri	es.		
		- 1		AT 0 -T	
Om 5/1	8/2023 0	at around	6:05PM, 1	nultiple custo	mers came
un from the d	Patlan alto	" eviting the	Train au	ining preighte	and and
up on wega	0,0	/	, , ,	1.0 -	noa, ana
yelling sayi	no that a s	erson on t	le train h	es a gun. We	immediately
1 . 16 0.	in antes a	An a	1 -		5° -
MODING/ NUU KA	regains, c	alled UVC	and Ira	mil rouce.	The alalome
yer an we go	1	roar and	was Truin	to exit the st	ation as
meno in suc	an up-		and have a day	10-10-114.90	
were in suc		1	n	0101 .	T 0.40
were in suc quickly as po		t more con	Idgivea	brief descrip	Tion of the
were in suc quickly as pe	asille, the	1	0	0. '	tionof the
were in suc quickly as pe individual	asille, the	t moore con thegun in	0	0. '	tion of the
were in suc quickly as pe individual	asille, the	1	0	0. '	tionof the
quickly as p individual	asille, the	1	0	0. '	tion of the
were in suc quickly as p individual	asille, the	1	0	0. '	tion of the
were in suc quickly as p individual	asille, the	1	0	0. '	tion of the
mere in suc quickly as pe individual	asille, tha whom had	1	0	0. '	tion of the
mere in suc quickly as pe individual	asille, tha whom had	1	0	0. '	tion of the
mere in suc quickly as pe individual	asille, tha whom had	1	0	0. '	tion of the Date: 5/18/2023
mere in suc quickly as pe individual	asille, tha whom had	t the gun in	Heir pos	JASSIGNED Days	Date: 5/18/2023
Blenmont	osille, tha whom had	1	0	0. '	Date: 5/18/2023
Employee Completing Rep Marian Subarront To Be Completed By Revie	osille, tha whom had	t the gun in	Heir pos	JASSIGNED Days	Date: 5/18/2023
Blenmont	osille, tha whom had	t the gun in	Heir pos	JASSIGNED Days	Date: 5/18/2023
Blenmont	osille, tha whom had	t the gun in	Heir pos	JASSIGNED Days	Date: 5/18/2023
Blenmont	essille, the whom had port wing Manager	tthe gun in	Heir pos	JASSIGNED Days	Date: 5/18/2023

Appendix A – RTRA Rail Supervisor and Station Manager Reports

Document 1 - Station Manager's Report Page 1 of 2

Incident Date: 05/18/2023 Time: 17:51 hours Final Report – Evacuation for Life Safety Reasons E23337

sustomer involved M Employee	cident description. Involved D With	229		
st Name, First Name			Emj	sloyee #
ite of Birth, Sex Home	Phone	Work Phone	Cell	Phone
N/A F	NA	N	A TA	NIA
ome Address N/A			Email Addres	NA
ture of Injury/Illness				
sistance Offered: Accepted 🗅 Declined	V			
ustomer was shaking	and cruinso	reliescherline	tothis incid	lent
Transported:		9-7-		
vspital: N/A	Ambulance	Number:	Arrival:	Departure:
ustomer Involved 🗅 Employee	Involved - Witne		10111	50 7 1
st Name, First Name N/A			Emj	loyee #
	Phone A	Work Phone	Call Call	Phone
MA MA	NIT	N,	Email Addres	NA
Anne Address N/J	4		Email Addres	VIA
ture of Injury/Illness	A			
sistance Offered: Accepted Declined				
• • • • • • • • • • • • • • • • • • •				
Transported:				
ispital: N/A	Ambulance	Number: A	Arrival:	Departure:
olice/Fire/Other Agencies Involv	red	and a state of the	1996	
NTPD /6:20 P.M.			Bad	mber
risdiction/Arrival Time				mber
MTPP /6'20 PM DESCRIBE THE INCIDENT (continu	ued of witness sta	entj. niciuus w	hat you are to come	the problem and
who you notified and when. Desc	ribe any property d			
"Refer to page #	ome. (1)			
for pope				
			7	
			Y	
			· · · · · · · · · · · · · · · · · · ·	

Document 2 - Station Manager's Report Page 2 of 2

.

1		l
	м	
. 1		

.

RTRA Supervisors' Report

DEPARTMENT OF OPERATIONS-RAIL SERVICE

metro	WASHINGTON METRO	POLITAN AREA TRANSIT AL	JTHORITY	Office	of Rail Transpo	rtation
Date: 5/18/2023	Incident Time Appr 6:05 pm	ox. Incident Location (Station Mezzanine#) Wheaton			Track/Mezzanine 182	
Equipment Number (1 Train 111	rain ID & Car Numbers;	Escalator/Elevator)				
Incident Description Station Shooting						
WMATA Personnel In	volved	Employee #	Rule Violation?	Home Divi	sion	Post Incident
Station Manager				Glenmont		NO
Arrival Time	Unit Number	Person In Charge		Remarks		L
6:15p	-	MTPD Forw	ard Liasion			
6:15pm- Transit a 6:29pm- Supervia 6:39pm- Supervia 6:40pm- Make co 6:55pm- Transit 1 6:56pm- Both Tr 7:19pm- Transit 1 7:25pm- Normal 7:30pm - Superv 7:40pm- Montgo scene to be comp 8:15pm- Montgo 9:20pm- Supervia	of shooting at Whe and Montgomery C sor mobile to sor on the sco on the sco ontact with Station 1 request for Test trai ansit and Montgom request track inspec service resumed by isor on scene mery County suspe promised. mery County assun mery County assun mery County homic sor Clear of s	ounty arrive on sec o Wheaton Station ene at Command P Manager to check on n to perform track ery County officer tion of track 2 in th passing Wheaton at e and assumes role nds service at Whe hes command of th cide and Detectives scene.	ost as RTRA Forv on him inspection of track s board train 713 he direction of Sha at a speed restricti- of RTRA Forwar- eaton due to excess e crime scene from s arrive on the scen	k 1 Glenmont. to perform track ady Grove from 6 on of 5mph d Liaison from S s wind coming fr n Transit ne to investigate.	Glenmont upervisor rom trains causir	ng crime
was mobile from	respond to Wheator the division to the he Station Manager	scene. Arrived on t	the scene and mad	e contact with th	e MTPD Forwa	rd Liaison

as at the discretion of transit. According to a briefing from Transit, a customer shot another customer exiting the training and escaped through the tunnel. Wounded victim was transported upon my arrival.

Supervisor Submitting Report (include payroll #)	Date 5/18/23	Report Reviewed by	Date

50.437 09/10REPORT MUST BE FAXED TO ROCC 301-618-1012 at end of tour

Document 3 - Rail Supervisor's Report. Page 1 of 1


Appendix B – Office of Emergency Preparedness (OEP) Report

Incident Date: 05/18/2023 Time: 17:51 hours Final Report – Evacuation for Life Safety Reasons E23337





SAFE OEP Incident Response Report



Document 1 – OEP Incident Response Report. Page 1 of 2

bmitte	

Incident Overview

Was Power removed: No

Red Tag (if applicable):N/A

Incident Narrative:

At 17:55 the ROCC received reports of shots fired inside of Wheaton Metro Station at the platform. The station was evacuated and closed. There will be no service between Silver Spring and Glenmont. A bus bridge was established to service between Silver Spring and Glenmont. Unified Command was established at the Wheaton kiosk at 18:04. All appropriate departments have been notified. The shooting victim was transported Medstar Montgomery by A742C with an unknown status. Train #713 performed a track inspection from Forest Glen to Glenmont and back from Glenmont to Forest Glen with a clear inspection reported. Rail resumed normal service bypassing Wheaton for police activity.

Incident Successes:

Communications.

Opportunities for Improvement:

N/A

Document 2 – OEP Incident Response Report Page 2 of 2

Incident Date: 05/18/2023 Time: 17:51 hours Final Report – Evacuation for Life Safety Reasons E23337

Appendix C – Root Cause Analysis

