

Remedial Action

Inspection Form

Washington Metrorail Safety Commission

Agency/Department Information

Agency/Department Ir	normation																
Inspection Date	YYYY/MM/DD							Report N	Report Number		14-\///	C-RRD-1					
inspection Date		2023/07/14							Report IN	Report Number		20230714-WMSC-RRD-1					
Rail Agency Name Wa			Washington Metropolitan Area Transit Authority									Name					
Rail Agency Department			SAFE						Rail Agency Department Contact Information		Rail Operations Manager (Rail 1) Missiona Assurance Coordinator (MAC) Fire Life Safety Officer (FLO)						
Inspection Location Car			rmen Turner Facility 3500 Pennsy Dr, Hyattsville, MD 20785														
nspection Summary																	
Inspection Activity #			1														
Activity Code			EMGT-GEN-OBS														
Inspection Units			1														
Inspection Subunits			1														
Defects (Number)			0														
Recommended Findi	ng		No														
Remedial Action Req	uired ¹		No														
Recommended Reins	pection									Yes							
Activity Summaries																	
Inspection Activity #	1	Inspection Sub			ubject ROCC					Activity Code		EMGT-GEN-OBS					
Job Briefing Employee Name/Title					Accompanied Inspector?			No	Out Brief Conducted	No Time				Outside Shift	No		
Related Reports	Emergence Fire Life Sa			nt and	d Related CAPS / Findings				WMSC-20-C0052 WMSC-21-C0162 WMSC-22-C0174 WMSC-22-C0176								
Related Rules, SOPs, Standards, or Other	Ref				Rule or SOP				Standard	•	Other / Title				Checklist Reference		
									NFPA 9 and 9.7		Council of Government/WMATA's Fire Liaison Program.			'A's	s		
Inspection Location	Main Track	Yard Station OCC		OCC	RTA Facility		WMSC Office	Track Type	At-grade Tunne		اد	Elevat	ed I	N/A			
						Х	х	(Х
Line(s) & Track Number			rner Facility 3500 Pennsy Dr, MD 20785			r,	Chain Marker and/or Station(s)			N/A	From		To N/A				
Vehicles	Head Car Number Number of C					er of C	ars AED Fire Ext			AED Fire Extin	inguishers. FAAP - Fire Alarm and Annunciator Panel. First						
	N/A				N/A Equipment			ent	Aid Kits. Big Board and PIDS.					-			
Description	The WMSC inspector conducted an inspection of the ROCC and the OEP d of the IMF. Incident Management Framework. All of the equipment insp compliance and operational. Fire Extinguishers were signed, and the ga the green. OEP was conducting training with Prince Georges Fire Departn Responders were completing a tunnel walk training with MTPD. Note: R was dispatched to a derailment of an AMTRAK train that was adjacent to property by an IDW. ROCC personnel monitored the incident throughout.											Number of Defects					
											Recommended Finding?				No	,	
												Remedial Action Required?				No	
									D. Note: Res adjacent to V	ponder(s).	Recommended Reinspection?				Ye	s	
Romodial Action									•								



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

A 6-	enderse + Manufacture - a <u>O</u> TH MALLER AN P. C. A front manual (= 400000 MODULAR and all Allermone O Manufact Lowerse, O a fact	ng paga na pananan 🚯 katananan (a. 🗮 ka	4 ± € 0 € 6 ± € 0 € (mm) mm eth. Einsteitete.	
		Live Headways		
	© Red Line 5.1 min 6.2 min 6.0 min	Orange Line	12.9 min 12.4 min 12.4 min 12.4 min 12.4 min 12.4 min 12.4 min	
	Guener Study Grove	Yellow Une	Green Line	
123 10:28.44 *cc	12.2 min 12.1 min Large Properties	10.0 mm E28 mm Head arms Room Avenues	Mann JAnn Genetit Brechter	
-	A = 8 9 V			

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

 Inspector in Charge's Signature
 Date

hispector in charge 5 signature		2023/07/14	
Inspector in Charge's Name Richard David	Inspection Team		