

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Donart Number	20230914-WMSC-RRD-1					
Inspection Date	2023/09/15	Report Number	20230314-WIVI3C-KKD-1					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	SAFE	Contact Information						
Inspection Location	Branch Ave Rail Yard 5700 Capital Gateway Dr. Camp Springs, MD 20746							

Inspection Summary

Inspection Activity #	1
Activity Code	EMGT-WI-PI
Inspection Units	1
Inspection Subunits	0
Defects (Number)	3
Recommended Finding	No
Remedial Action Required ¹	Yes
Recommended Reinspection	Yes


Activity Summaries


Inspection Activity #	1	Ins	pection Sub	on Subject Branch Ave Yard			all Protection	Activity Code				EMGT-WI-PI			
Job Briefing Employee Name/Title	Yes. Both a safety in brief and out brief was conducted.			Accompanied Inspector?			Yes	Out Brief Conducted	Yes	Time					No
Related Reports	Previous Branch Rail Yard Inspections. Additional information on Vector report # 5800			Related CAPS / Findings			WMSC-22-C016	/MSC-22-C0169 WMSC-22-C0170							
	Ref		Rule	or SOP			Standard		Other / Title				Checklist Reference		
Related Rules, SOPs, Standards, or Other	Fall Protection Policies. Fall protection Memorandum. Agency Safety Plan Industrial Hygiene and Occupational Safety and Health Training						OSHA/MOSH Fall Protection.		Emergency Action Plans.				Fall Protection Procedures.		
Inspection Location	Main Track	Yard	Station	occ	RTA F	acility	WMSC Office	Track Type	At-g	rade	Tunnel		Elevated		N/A
		Х													Х
Line(s) & Track Number	Branch Ave R Dr. Camp Spr			l Gateway	Chain Ma Station(s	rker and/	or		From				То		
Nullibei						, 1		N/A	N/A						
Vehicles	Head Car I		N	umber of (uars	Equipme	provided). Fire quipment Equipment, Fire			on equipment. (Current Memorandum and procedures were re Life Safety Equipment. First Aid, AED KIT, Fall Protection Fire Extinguishers, Eye Wash Station, signage, Lighting, room, FAP, and Spill Kits and that the proper PPE is being					
	The WMSC inspectors conducted a focused unannounced Risk Based Inspection on Fall Protection. During the inspection the WMSC inspectors conducted an additional spot inspection of some FLS equipment and Emergency response Plan documentation.								Number of Defects					3	
Description									Recommended Finding?					No	,
	mispection of some 123 equipment and Emergency response Plan documentation.							Remedial Action Required?					Yes	5	
							Recommended Reinspection?					Yes	s		
Remedial Action	Correction imn	nediate Life	Hazards (N	one noted)	Correct all o	ther defici	iencies.								

Washington Metrorail Safety Commission

Photos:

20230914_075717.jpg_FDC_sign
















20230914_082240.jpg_EM_Procedures



20230914_082257.jpg_EAP



5



Dian Number: 4400-3-19-00

W. Other Business - Green the Shadoom is by all affect which is project curerly tree is no transcribed for doing of parcetic for doing for doing of parcetic for doing of parcetic for doing of parcetic for doing for doing

Hot Work Permit - Annual
HWP23-013

Cpiration Date: 08/31/2024

Cility Address: 5700-B Capital Galeway, Suitland, MD

Cation / Building: BLDG-B Service & Inspection Shop

Duane T. Perry

WMATA Fire Marshal




20230914_085319.jpg_AED



20230914_085405.jpg_Fall_Protection













20230914_091309.jpg



20230914_091353.jpg_Clean_work_Area





20230914_091434.jpg_Eye_Protection_up_to_date




20230914_092345.jpg












 $\underline{24.5760_20230914_084314} redacted for inspection report_5760.jpg$



24.5760_20230914_084857_redacted_for_inspection_report_5760.jpg





24.5760_20230914_085436_redacted_for_inspection_report_5760.jpg



 $24.5760_20230914_0932\underline{18}_redacted_inspection_report_5760.jpg$



The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2023/09/15
Inspector in Charge's Name	Inspection Team	
Richard David	Manny Lopez	