

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Daniel Ministry	20220022 WMSC DDD 1				
	2023/09/25	Report Number	20230922-WMSC-RRD-1				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	SAFE	Contact Information					
Inspection Location	Carmen Turner Facility 3500 Pennsy Dr, Hyattsville, MD 20785						

Inspection Summary

Inspection Activity #	1
Activity Code	EMGT-TNG-OBS
Inspection Units	1
Inspection Subunits	0
Defects (Number)	2
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Ins	ection Subj	ect	ROCC training				Activity Code			EMGT-TNG-OBS				
Job Briefing Employee Name/Title				Accompanied Inspector?			No	Out Brief Conducted	No	Time				Outside Shift	No	
Related Reports	Previous RO reports. Rai	Related CAPS / Findings WMS0			WMSC-C0054 V	C0054 WMSC-C0166 WMSC-C0169										
Related Rules.					e or SOP S				Other / Title				Checklist Reference			
SOPs, Standards, or Other									Agency Safety Plan Training Requirements. Section 5.1 Competencies and Training.							
Inspection Location	Main Track	Yard	Station	occ	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunne		el Elevat		ed 1	N/A		
				Х												
Line(s) & Track Number	Carmen Turner Facility 3500 Pennsy Dr, Hyattsville, MD 20785 Chain Marker and/					or Station(s)	From N/A N/A					To	То			
	Head Car	Number	N	umber of 0	Cars			FLS equipmen	t was obse	erved. De	eficiencies N	encies Noted: 1. MSRPH book				
Vehicles	N/A			N/A		Equipment (located in the			longer in effect were still being used for RWP training. e Training Lab). 2. Some items in the IMF glossary have ated and does not reflect current practices.							
	The WMSC inspectors conducted an unannounced inspection of several areas at the ROCC. These inspections included Training, Fire Life Safety equipment and an onsite visit for the Railcar Audit.									Number of Defects					2	
Danasistias										Recommended Finding?					No	
Description	visit for the nancal Addit.								Remedial Action Required?					No		
					Recommended Reinspection?					Yes	Yes					
Remedial Action										·	·					

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2023/09/25					
Inspector in Charge's Name Richard David	Inspection Team Bruce Walker Tiffany Minor Fred Diven John DeRenzo						