



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD 2023/10/26	Report Number	20231025-WMSC-RRD-1
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	SAFE	Contact Information	
Inspection Location	Metro Intergrated Command & Communication Center (MICC). 2401 Mill Rd Alexandria VA 22314		

Inspection Summary

Inspection Activity #	1
Activity Code	EMGT-GEN-OBS
Inspection Units	1
Inspection Subunits	0
Defects (Number)	2
Recommended Finding	No
Remedial Action Required¹	Yes
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Inspection Subject	MICC Facility				Activity Code	EMGT-GEN-OBS			
Job Briefing Employee Name/Title	No	Accompanied Inspector?	No	Out Brief Conducted	No	Time		Outside Shift	No		
Related Reports	Previous ROCC Inspections at The Carmen Turner Facility.		Related CAPS / Findings			WMSC-20-C0054 #4 & 5 WMSC-22-C0163 #3 & 4 WMSC-22-C0166 #3 WMSC-22-C0167 #1 WMSC-22-C-174 #1 & 2					
Related Rules, SOPs, Standards, or Other	Ref	Rule or SOP		Standard		Other / Title		Checklist Reference			
	NFPA IFC										
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
				X							X
Line(s) & Track Number	Metro Intergrated Command & Communication Center (MICC). 2401 Mill Rd Alexandria VA 22314			Chain Marker and/or Station(s)			From		To		
							N/A		N/A		
Vehicles	Head Car Number		Number of Cars		Equipment	MICC lay out, Big Board, Monitors, AED, Fire Extinguisher, First Aid Kit, Exit/Exits Signs, CBEMIS, PID, Power Board (newly added). Leaders in the Room: Metro 1, Rail 1, Comm 1, Mission Assurance Coordinator (MAC), Fire Liaison Officer, (FLO), Video 1.					
	N/A		N/A								
Description	The WMSC inspectors conducted a general inspection of the new facility. This inspection focused on the MICC while observing a few additional areas (MOC/ELES). We also note a few fire life safety items.						Number of Defects		2		
							Recommended Finding?		No		
							Remedial Action Required?		Yes		
							Recommended Reinspection?		Yes		
Remedial Action	Replace Cap on the freestanding fire department connection. Label fire extinguisher cabinet and sign fire extinguisher in the MICC. Both items reported to the Fire Marshal.										




Inspection Form

Form WMSC-IR-1


Washington Metrorail Safety Commission

Photos:

20231025_124325.jpg



20231025_125638.jpg





Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

20231025_125650.jpg



20231025_131159.jpg





Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

20231025_131812.jpg



20231025_134021.jpg





Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

20231025_134026.jpg



20231025_143543.jpg





Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

20231025_150750.jpg



20231025_145829.jpg





Inspection Form


Form WMSC-IR-1

Washington Metrorail Safety Commission

20231025_1



20231025_131726.jpg





Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

20231025_143042.jpg



Inspection_6160_redacted.jpg



¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2023/10/26
Inspector in Charge's Name Richard David	Inspection Team Allen Freeman	