

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Increation Date	YYYY/MM/DD	Danient Normber	20240901-WMSC-RRD-1					
Inspection Date	2024/01/11	Report Number	20240301-MINI3C-VVD-1					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	SAFE	Contact Information						
Inspection Location	Metro Intergrated Command & Communication Center (MICC). 2401 Mill Rd Alexandria VA 22314							

Inspection Summary

Inspection Activity #	1
Activity Code	EMGT-GEN-OBS
Inspection Units	1
Inspection Subunits	0
Defects (Number)	2
Recommended Finding	No
Remedial Action Required ¹	Yes
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Ins	pection S	ubject	t MICC Facility				Activity Code			EMGT-GEN-OBS			
Job Briefing Employee Name/Title	N/A			Accompanied Inspector?			No	Out Brief Conducted	No	No Time			Outside Shift		
Related Reports	Previous MICC report Previous ROCC reports.			Related CAPS / Findings			WMSC-20-C0054 #4 & 5 WMSC-22-C0163 #3 & 4 WMSC-22-C0166 #3 WMSC- 22-C0167 #1 WMSC-22-C-174 #1 & 2								
Related Rules,	Ref			Rule or SOP			Standard		Other / Title			C	Checklist Reference		
SOPs, Standards, or Other	IFC NFPA														
Inspection Location	Main Track	Yard	Statio	n OCC	RTA Facility		WMSC Office	Track Type	At-grade Tunnel		el E	Elevated N/A			
				Х										Х	
Line(s) & Track	Metro Inter	-								From			То		
Number	Communication Center (MICC). 24 Rd Alexandria VA 22314			2401 Mill	01 Mill Chain Marker and/o		or Station(s) N/A		N/A			N/A			
Vehicles	Head Car	Number		Number of 0	lumber of Cars			MICC layout, E	Big Board, Monitors, AED, Fire Extinguisher, First Aid Kit,						
	N/A N/				Equipment			Exit/Exits Signs, CBEMIS, PID, Power Board.							
	The WMSC inspector conducted a general inspection of the MICC. This inspection								Number of Defects					2	
Description	focused on the MICC's operations while observing additional fire life safety items.									Recommended Finding?				No	
										Remedial Action Required?				Yes	
									Recommended Reinspection?					Yes	
Remedial Action	1. Label fire extinguisher cabinet. 2. Update and sign fire extinguisher in the MICC, (Attached photos).														



Photos: 20240109 111813.jpg



20240109_ 111802.jpg





Inspection Form

Form WMSC-IR-1
Washington Metrorail Safety Commission

20240109 _111822.j pg



1 The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature	Date 2024/01/11	
Inspector in Charge's Name Richard David	Inspection Team N/A	