

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

0-41-4								
Inspection Date	YYYY/MM/DD	Donast Number	20240516-WMSC-DLB-1					
	2024/05/16	Report Number						
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	Safety	Contact Information						
Inspection Location	Silver Spring Field Office 1407 East - West Highway Silver Spring, Maryland 20910							

Inspection Summary

Inspection Activity #	1
Activity Code	OBS-SAFE-TNG-QAI
Inspection Units	1
Inspection Subunits	
Defects (Number)	7
Recommended Finding	Yes
Remedial Action Required ¹	Yes
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1 Inspection Sul			ect	ct MTS ACS Safety Orientation (Purple Line.)			Activity Code			OBS-SAFE-TNG-QAI					
Job Briefing Employee Name/Title	Yes.			Accompanied Inspector?		Yes	Out Brief Conducted	Yes Time				Outsid Shift				
Related Reports	N/A. Rela			Related CA	ated CAPS / Findings N/A.							-				
Related Rules,	Ref Rul			ule or SOP Standard			Standard		Other /	Checklist Reference						
SOPs, Standards, or Other	N/A.		TO-2	O-24-04 Summer Shutdown ACS		N/A.	N/A.		N/A.			N/A.				
Inspection Location	Main Track	Yard	Station	occ	RTA Fa	acility	WMSC Office	Track Type	At-grade		Tunnel		Elevat	Elevated N,		
					Х									Х		
Line(s) & Track Number	Silver Spring Highway Silv	0			Chain Ma		or		From				То			
Number	,	1 0,			Station(s)			N/A.				N/A.				
Vehicles	Head Car N/	Number 'A.	N	umber of C N/A.	.ars	Equipm	ent	N/A.								
	BACKGROUND/PURPOSE: On Thursday May 16, 2024, the WMSC attendant a Purple Line							Number of Defects					7			
	project site "ACS Safety Indoctrination Briefing." During the Purple Li Metrorail contractor - Maryland Transit Solutions (MTS) will be respo												Yes			
	zone located on the Redline located from the Silver Spring Station to the Spring Street								Remedial Action Required?						Yes	
Description	Bridge. The Metrorail Shutdown is scheduled to last from Saturday June 1, 2024, to Monday August 26,2024. Therefore, to be granted access into the Authorized Construction Site (ACS), personnel must attend the Mandatory ACS Safety orientation. METHOD: The WMSC Team attended the Purple Line project site ACS Safety Indoctrination Briefing and made observations and took notes. Observations/SAFETY CONCERNS: After coordination of the observations and notes a discussion generated a list of several items of note. 1. The briefing did not provide any details on the emergency response/action plans. Similar briefings typically provide the information that personnel on site need to know in order to properly report, respond to, and understand communication in the event of an emergency. 2. The briefing did not cover communication and notification of emergencies to WMATA (which therefore would impede notification to the WMSC). As you noted, it is important to include this information as well as the Level 1/2/3 information from the plan and the situations where the ACS would no longer apply and how that would be communicated. The briefing's drug and alcohol testing information also did not appear to match Metrorail requirements, or requirements in the event of an accident. 3. The briefing did not sufficiently cover safe work around moving vehicles. The sole mention was to be clear when told to clear. This is not sufficient protection for roadway workers, and it is not clear whether any such safety rules exist. 4. The briefing did not cover likely hazards during this work, such as heat hazards. 5. The briefing generally mentioned third rail hazards did not mention where WSADs would be present and what to do if one alarms.							Recommended Reinspection?					Yes			
Remedial Action	Mitigations to	be presente	ed to the WM	ISC by Metro	orail on Wed	nesday, 2	2, 2024. There	fore, remediation	is in a pendi	ng status.						

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2024/05/16
Inspector in Charge's Name Darrell Braxton	Inspection Team Bruce Walker Manny Lopez Richard David Max Smith Fred Diven	