

## **Inspection Form**

Form WMSC-IR-1

Washington Metrorail Safety Commission

## Agency/Department Information

Insuration Date	YYYY/MM/DD	Daniel Million ben	20240724-WMSC-MAL-1	
Inspection Date	2024/07/26	Report Number	20240724-WWSC-WAL-1	
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name	
Rail Agency Department	CMNT	Contact Information		
Inspection Location	New Carrollton S&I Shop - Railyard D99 4300 Garden C	City Dr Hyattsville, MD 20785		

## **Inspection Summary**

Inspection Activity #	1
Activity Code	VM-WI-PI
Inspection Units	1
Inspection Subunits	1
Defects (Number)	3
Recommended Finding	Yes
Remedial Action Required <sup>1</sup>	No
Recommended Reinspection	No

## **Activity Summaries**

Job Briefing   Employee   Name/Title   WMATA Inspection   Accompanied Inspector?   No   Out Brief   Yes   Time	07	:30 AM	Outside				
	·		Shift	No			
Ref Rule or SOP Standard Other / Title		Checklist Refer		rence			
Related Rules, SOPs, Standards, or Other  METRORAIL OPERATING RULEBOOK FIRST EDITION Effective: Sept 1, 2023, Safety Rules  N/A  N/A  N/A	N/A		N/A				
Inspection Location Track Office Track Type	Tunnel	Eleva	ted	N/A			
X			Го				
Line(s) & Track     New Carrollton S&I Shop - Railyard D99     Chain Marker and/or Station(s)     From       Number     4300 Garden City Dr Hyattsville, MD 20785     Station(s)     N/A	From N/A						
Head Car Number Number of Cars							
Vehicles N/A N/A Equipment N/A							
WMSC Inspector conducted a rules compliance inspection of the New Carrollton S&I Shop Number of Defects			3	3			
and Yard for compliance with the Metrorail Operating Rules and Procedures Handbook (MOR), including Preventive Maintenance Inspections (PI) activities. General	Recommended Finding?			'es			
Information: Met with the Supervisor from the Inspection Office, QA Incident  Remedial Action Required	Remedial Action Required?		N	No			
Carrollton S&I shop, and the following observations were noted. New Carrollton S&I Shop and Yard - There were numerous railcars on the floor and on lifts, but there were no mechanics working on them. There were no mechanics on the floor for the duration of the three-hour visit.	Shop and Yard - There were numerous railcars on the floor and on lifts, but there were no mechanics working on them. There were no mechanics on the floor for the duration of the three-hour visit Defect #1 - Lights in the blow pit area were blinking on and off continuously. Blinking lights are very distracting for mechanics working on the floor. See Attached Photo #1 Defect #2 - The car wash alarm was going off continuously. This alarm can set an unsafe sense of complacency and cause mechanics to ignore real alarms while working on the floor. It was stated that the car wash was decommissioned						
Remedial Action							

<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature	Date 2024/07/26	
Inspector in Charge's Name Manuel Lopez	Inspection Team N/A	