

# **Inspection Form**

Form WMSC-IR-1

Washington Metrorail Safety Commission

## Agency/Department Information

Inspection Date	YYYY/MM/DD	Danient Normalian	20240820-WMSC-MAL-1			
	2024/08/23	Report Number				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name			
Rail Agency Department	CMNT	Contact Information				
Inspection Location	Brentwood S&I Shop - Railyard B99 601 T Street NE Washington DC 20002					

### **Inspection Summary**

Inspection Activity #	1
Activity Code	VM-WI-PI
Inspection Units	1
Inspection Subunits	1
Defects (Number)	1
Recommended Finding	Yes
Remedial Action Required <sup>1</sup>	
Recommended Reinspection	No

### **Activity Summaries**

Inspection Activity #	1	1 Inspection Subject			ct Observation 7K SMP and SMD process				Activity Code			VM-WI-PI			
Job Briefing Employee Name/Title	Yes			Accompanied Inspector?			Yes	Out Brief Conducted	Yes Time		02:30 PM		Outside Shift	No	
Related Reports	N/A			Related CA	APS / Findin	gs		N/A							
Related Rules, SOPs, Standards, or Other	Ref		Rul	e or SOP Sta			Standard		Other / Title			Checklist Reference			rence
	METRORAIL RULEBOOK F Effective: Se Safety Rules	IRST EDITION Pt 1, 2023,				N/A		N/A				N/A			
Inspection Location	Main Track	Yard X	Station	осс	RTA Facility		WMSC Office	Track Type	At-grade		Tunnel		Elevated		N/A
Line(s) & Track	Brentwood S	S&I Shop - F	•	99 601 T		rker and/o	or		From				То		
Number	Street NE Washington DC 20002			Station(s)			N/A				N/A				
Vehicles	Head Car		1	Number of C	Cars	Equipme	ent	N/A							
Description	WMSC Inspectors conducted a rules compliance of the Brentwood S&I Shop and Yard in compliance with the Metrorail Operating Rules and Procedures Handbook (MOR), including Preventive Maintenance Inspections (PI) activities. The following observations were noted General Information: WMSC inspectors met with personnel from the CMNT Inspection Office, Truck shop, Scheduled Maintenance Program (SMP), and the Wheel Replacement Program (WRP). The following observations were noted WMSC conducted an afternoon visit of the Brentwood S&I shop. WMSC noticed a very busy S&I Shop where personnel were actively working on numerous tasks. There were numerous railcars and trucks on the floor and on lifts being overhauled, there was equipment being transported via cranes, there was work being done on the SMP and WRP process, there where wheel press operations being conducted, and there were numerous mechanics working on them. This was a very active shop for the duration of the two-hour visit Discussed the status of the wheel pressing process for 7K railcars. The wheel press machine at Brentwood is operational. Wheel press operators stated that have not had any misfits while pressing wheels during the last 2 and ½ months. Both Brentwood personnel gave credit to the high success rate on choosing wheels with a high surface roughness factor of RA 120 or greater. They also stated that all imperfections need to be removed from both the wheels and axles. This is done by hand via metal sandpaper Discussed the status of the Scheduled Maintenance Program (SMP). Two trucks were being overhauled for the SMP program and one truck was being overhauled for the WRP. Currently installation of overhauled components is on hold pending the lack of parts. Three MPs are going through the SMP process, 7044-45, 7178-79, and 7160-61 CMNT stated that Quality Assurance has requested the disassembly of one wheelset that has gone through the WRP. No justification was provided.									1 Yes					
Remedial Action	J		- ,		,										
Remedial Action															

<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2024/08/23
Inspector in Charge's Name	Inspection Team	



# **Inspection Form**

Form WMSC-IR-1
Washington Metrorail Safety Commission

Manuel Lopez	Bruce Walker	
ı		