

# **Inspection Form**

Form WMSC-IR-1

Washington Metrorail Safety Commission

## Agency/Department Information

Increation Date	YYYY/MM/DD	Donout Number	20240927-WMSC-DLB-1				
Inspection Date	2024/09/27	Report Number	20240927-WW3C-DLB-1				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	RWP	Contact Information					
Inspection Location	Branch Avenue Metro Station (F99) 4704 Old Soper Road, Suitland-Silver Hill, MD 20746						

### Inspection Summary

Inspection Activity #	1
Activity Code	OBS-SAFE-TNG-QAI
Inspection Units	1
Inspection Subunits	0
Defects (Number)	4
Recommended Finding	Yes
Remedial Action Required <sup>1</sup>	Yes
Recommended Reinspection	Yes

### **Activity Summaries**

Inspection Activity #	1	Ins	pection Subj	ject	RWP Safe	ty Stand	Down Train	ing	Activity Code			OBS-SAFE-TNG-QAI				
Job Briefing Employee Name/Title	Yes	•		Accompan	ied Inspecto	or?	No	Out Brief Conducted	Yes <b>Time</b>			07:00 AM		Outside Shift	Yes	
Related Reports	Protection (I	C- 2024 Roadway Worker ction (RWP)Audit Related CAPS / Findings N/A.														
	Ref		Rule	or SOP			Standard		Other / Title			Checklist Reference				
Related Rules, SOPs, Standards, or Other	September 2 regarding M future Road Protection P Revisions.	letrorail's way Worke	PO-2 PO-2 Req	24-08 - App 24-10 - Trar 24-25-Bulle uired Docu Intrust Tok	nsfer of Aut tin Orders mentation	hority &	N/A.		N/A.				N/A.			
Inspection Location	Main Track	Yard	Station	occ	RTA F	acility	WMSC Office	Track Type	At-grade Tunne		el	Elevated		N/A		
		Х													Х	
Line(s) & Track	Branch Aven Old Soper R				Chain Ma		or		From				То			
Number	20746	<i>,</i>		<i>,</i>	Station(s			N/A.				N/A.				
Vehicles	Head Car		N	umber of C	Cars	Equipm	ent	N/A.								
	N/A		<u> </u>	N/A.	• • • • • • • • • • • • • • • • • • • •			, , , , , , , , , , , , , , , , , , ,						_		
	BACKGROUND: A meeting was held between Metrorail and the WMSC on Thursday September 26, 2024. The meeting was conducted via Zoom and was in response to													4		
	Metrorail's request. The meeting was predicated on the need to clarify the WMSCs								Recommended Finding?  Remedial Action Required?					Yes		
Description	Metrorail's request. The meeting was predicated on the need to clarify the WMSCs concerns that were conveyed via an email response sent to the Rail Transit Agency (RTA) on Thursday September 19, 2024. The specific concerns were listed in report 20240909-WMSC-DLB-1. The WMSC met with the RTA to hear Metrorail's explanations on the following areas involving its Roadway Worker Protection (RWP) program. Below is a list of the areas: -Metrorail's Strategy for the RWP program -How proposed changes come about -How the proposed changes are considered against the overall RWP program &£C Safety Assessment conducted for each proposed change Additionally, data and situations that led to the cited hazards mentioned in the recent RWP Safety Stand Down) list: 1. Workers Utilizing RWP when there is no risk 2. Diverted attention of the Rail Traffic Controllers (RTC(s)) 3. Devaluation of the RWP when hazards are not present RESULTS OF THE MEETING: Information that was discussed during the meeting minimally provided clarification for the areas listed earlier in this report. Consequently, the WMSC issued an order to Metrorail on Friday September 27, 2024. The order permitted Metrorail to put into effect on Tuesday October 1, 2024, all permanent orders discussed during the Safety Stand Down Training. The 2024 RWP Audit that the WMSC conducted of the Metrorail system resulted in 13 findings. During the audit, WMSC Inspectors observed unsafe implementation, contradictory procedures and policies at all sites inspected during the RWP Audit. As a result, 13 corrective action plans are being developed to mitigate the safety concerns identified by the WMSC. Additionally, the order is further connected to the 2024 RWP Audit as it addresses the frequent changes made to RWP rules that creates unique problems for Metrorail's RWP program. The goal of the order is to ensure that Metrorail administers changes to its RWP rules, procedures, and policies in an annual and comprehensive fashion. In addition, permission and approval must be granted fr						ended Rei	nspection?			Ye	:5				



# **Inspection Form**

Form WMSC-IR-1

Washington Metrorail Safety Commission

	The WMSC issued an order to ensure that Metrorail administers changes to its RWP rules, procedures, and policies in an annual and comprehensive fashion. In addition,
	permission and approval must be granted from the WMSC after a thorough review before new RWP rule changes can be enacted by Metrorail.

1 The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2024/09/27
Inspector in Charge's Name Darrell Braxton	Inspection Team N/A.	