

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY MM DD			Report Number	20200828-WMATA-KEK-16				
	2020	08	28	Report Number	20200828-WWATA-KEK-16				
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	Signals & ATC	Sub- Department ATC		ATCIN	
Rail Agency Department	Name			Email	Office Phone Mo		lobile Phone		
Contact Information									
	WMATA - Technical Skills and Maintenance Training (TSMT) Department								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	STC-RR-TNG					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	YES					
Remedial Action Required ¹	NO					
Recommended Reinspection	YES					

Activity Summaries

Inspection Activity #	1	Inspec	pection Subject Records			Review – Q&A for Compliance				Activity Code		STC		RR	TRG
Job Briefing Employee Name/Title	None Required				Accompanied Inspector?		Out Brief Conducted	N/A	Time	N/	Α	Outside Shift	N/A		
Related Reports	Trainining & Certification Audit				Related CAPS / Findings FTA Finding T			OC-ATC & Signals Report 09/20/2018 - Element #16							
	Ref Ru			Rule or S	Rule or SOP			tandard		Other / Title		Checklist Reference			
Related Rules, SOPs, Standards, or Other	ATC 3 Audit - Training											ATCM Training Re		Records	
	Mai Trac		Yard	Stati	ion (осс	RTA Facility	WMSC Office	Track Type	At-grade Tunnel		Elevated		N/A	
Inspection Location									паск туре						
Line(s)	NI/A	N/A Track			N/A C		Chain Ma	hain Marker		From			То		
Line(s)	Num		Numbe	er	IV/A		and/or Station(s)		N/A	N/A N			N/A		
	Head Car Number				Number of Cars				N/A						
Vehicles	N/A				N/A		Equip	ment							
Description			-		-		espect to the - TOC Triennial Audit of			Number of Defects					0
Description	Auto	matic Tr	ain Cont	rol (A	TC) and S	ignals F	inal Safety	and Securit	y Report:	Recommended Finding?					NO

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
KEMMERY ELAENE KENDRICK		August 28, 2020
Inspector in Charge – Name	Inspection Team	
KEMMERY E. KENDRICK	WASHINGTON METRO SAFETY OVERSIGHT COMMISSION	

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	September 20, 2018. Audit Findings #1. – ATC'S Branch Maintenance Control	Remedial Action Required?	NO
	Policy (BMCP) lists the ATC the ATC Journeyman Course as required training for ATC Represented (Union) personnel. This training has not been provided since 2015. PURPOSE: To validate that ATCM Represented Personnel are compliant with the appropriate training required in the TOC 3-year Safety and Security Report. The report states that "other BMCP mechanic training requirements for ATC Cranking and Blocking Certification and the ATCM Journeyman course do not appear in the roster. The Journeyman training required by the BMCP was not being provided for the training period reported." Findings & Deficiencies: 1. The Cranking and Blocking Certification is not appearing in the roster as stated in the TOC report to date. After speaking with the director of training, who informed me by phone that Cranking is embedded in onthe-job instruction. Blocking has been replaced with a Clamping technique which is also imbedded in OIT program. See WMATA Department of Safety and Environmental Management Safety Bulletin SB #17-09a, September 2017, included in report. 2. The recommended Journeyman Training has restarted and is ongoing with one hundred-eight six (186) ATCM personnel completing Phase I, and forty (40) completing both Phase I, and Phase II part 1. Information has been provided showing the training was reenacted 2019; satisfying the recommended corrective action in which WMATA was to implement a new technical training program for all ATC Mechanics that did not receive Journeyman training.	Recommended Reinspection?	YES
Remedial Action	Follow-up inspection for continued progress slated for February 2021		





Form WMSC-IR-1 Version date: 10/5/18