

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20203020-WMATA-KEK-26					
inspection Date	2020	09	30	Report Number						
Rail Agency Name	Washington Authority	Metropolitan	Area Transit	Rail Agency Department	Signals & ATC	Sub- Dep	partment	ATCIN		
	ı	Name		Email	Office Phone	е	N	Mobile Phone		
Rail Agency Department Contact Information						•				
		<u> </u>								
Inspection Location	E08 – PG Plaza - Green Line									

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	STC-RR-TNG					
Inspection Units	1					
Inspection Subunits	5					
Defects (Number)	0					
Recommended Finding	NO					
Remedial Action Required ¹	NO					
Recommended Reinspection	NO					

Activity Summaries

Inspection Activity #	1 Inspection Subject ATCM LEVEL #1 Supervis			EVEL #1 Superviso	r Complian	e Checks	Activity Code		STC	RR	TNG
Job Briefing Employee Name/Title	None Required			Accompanied Inspector?	N/A	Out Brief Conducted	N/A	Time	1:00p	Outside Shift	N/A
Related Reports	Tri-State Oversight – Final Report Rela			Related CAPS / F	06 – (FTA Safety Directive 16-2)						
	Ref	f Rule or SOP		Standard Other / Title			itle	Checklist Reference		ence	
Related Rules, SOPs, Standards, or Other	ACTN	M OSS, Compl, OJT	ACTM QC Policy				MAXIMO		Fo	Form-Revised Nov, 2018	
Standards, or Strict	TOC-	ATC-15-06		•					Ne	New Electronic Forms	

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
KEMMERY E. KENDRICK		SEPTEMBER 30, 2020
Inspector in Charge – Name	Inspection Team	
KEMMERY E. KENDRICK	WASHINGTON METRO RAIL SAFETY COMMISSION	

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Inspection Location	Main Track	Yard	Station	осс	RTA Facility	WMSC Office	Track Type	At-grade	Tui	nnel	Elevated	Interlock	
							nack Type					х	
Line(s)	N/A Track		N.	<i>,</i> Δ	Chain Marker			From			То		
Line(3)	<u>'''</u>	Numb	er '''	^	and/or St	ation(s)	CM - 388 + 50)	CM - 425 + 90				
	Head Ca	r Number	Num	ber of Cars									
Vehicles	N	/ A		N/A	Equip	ment	N/A						
		-			•	afety Directi	ve 16-2) -	Number of Defects				0	
		Action Item; Quality Control Spot Checks of Supervisors' Work								Recommended Finding?			
		PURPOSE: 1. Level I - Quality control check for compliance (Field Audits). Inspection							Remedial Action Required?				
Description	Field Audit. Actionable Item Recommendation accepted by ATCM to have Region Managers and Shift Supervisors spend 50 percent and 75 percent, respectively, of their duty day in the field conducting the following activities: Facility inspections Safety observations Level 1 and Level 2 ATCM Compliance Checks, as applicable Observations of PMIs being performed, and reinstructing employees as needed Observations of corrective maintenance being performed Observations of pre-job safety briefings, and Observing the quality of work in the field Conducting ATCM compliance audits Evaluating, retaining (if necessary) and enhancing the professional development of assigned employees Activity #1 – 07:00(pm) – MAXIMO CC: Work Order #1547&18-01/08/2020 Interlocking Inspection Supervisor reports that employee conducted all inspections successfully, and is all activities followed per WMATA SOPs and regulations. Location: E08 PG Plaza Interlocking						Recommend	Recommended Reinspection?					

Form WMSC-IR-1 Version date: 10/5/18