

Inspection Form

Washington Metrorail Safety Commission

Form WMSC-IR-1

Agency/Department Inforr	nation
--------------------------	--------

Inspection Date	YYYY/MM/DD 2021/05/04	Report Number	20210423-WMATA-KEK-12					
Rail Agency Name	Washington Metropolitan Area Transit Authority		Name					
Rail Agency Department	Signals and ATCM	Rail Agency Department Contact Information						
Inspection Location	Teams Virtual	ms Virtual						
Inspection Summary								
Inspection Activity #		1						
Activity Code		STC-MTG-GEN						
Inspection Units		1						
Inspection Subunits		0						
Defects (Number)		1						
Recommended Finding		Yes						
Remedial Action Required ¹	Yes							
Recommended Reinspection		Yes						
A still it. Commencies								

Activity Summaries

Inspection Activity #		Insp	ection Sub	ject				Activity Code			STC-MTG-GEN				
Job Briefing Employee Name/Title					Accompanied Inspector?			Out Brief Conducted	Yes Time					Outside Shift	No
Related Reports	20210318-WMATA-KEK-07 2020811-WMATA-KEK-12			Related CAPS / Findings			TOC-ATC-15-002								
Related Rules,	Ref		Rule	e or SOP			Standard		Other / Title			Checklist Reference			ence
SOPs, Standards, or Other															
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility		WMSC Office	Track Type	At-grade Tunn		nel Eleva		ed I	N/A	
															Х
Line(s) & Track Number	Teams Virtu	ual			Chain Ma	rker and/	or Station(s)	From N/A			To N/A				
Vahialaa	Head Car Number			lumber of Cars				NI (A							
Vehicles	N/A N/A					Equipment N/A									
	N/A									Number of Defects					
Description										Recommended Finding?				Ye	S
2									Remedial Action Required?					Ye	-
										nded Rein	•			Ye	-
Remedial Action	The ATC Branch and SAMS must conduct a full inventory of ATC tools in order to scrub Maximo and its tracking list of all tools no longer being used. The ATC Branch or SAMS must provide a revised Maximo inventory list with obsolete tools removed and regained calibration compliance. Also, the ATC Branch and SAMS must develop a documented tool distribution control method so that new equipment/tools are not issued until old ones are returned, and the person receiving the old equipment removes it from the inventory and maintenance cycle in Maximo.														

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

 Inspector in Charge's Signature
 Date

 2021/05/04
 2021/05/04

		2021/05/04
Inspector in Charge's Name	Inspection Team	
Kemmery Kendrick	N/A	