

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

0						
Inspection Date	YYYY/MM/DD	Report Number	20210519-WMATA-LBW-1			
	2021/05/19		20210519-WMATA-LBW-1			
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department Contact Information	Name			
Rail Agency Department	Rules committee					
Inspection Location	Microsoft Meeting					

Inspection Summary

1
RTRA-GEN-MTG
1
0
0
No
No
No

Activity Summaries

Dib Briefing Employee Name/Title NA Related CAPS / Findings NANA	08:6	00 AM S	Reference			
Related Rules, SOPs, Standards, or Other Related Rules, SOPs, Standards, or Other NA NA NA NA NA NA NA NA NA N			Reference			
Related Rules, SOPs, Standards, or Other NA NA T-20-31 Power Energization Verification Rev 3 T-21-15 Crew Support T-21-12 Green Line ACS T- 21-14 Green Line TPSS/TBS T-21- 21 Remove Operating Rule 3.16 T- 21-22 Storage Class 1 Rail Vehicles T-21-24 Fire and Smoke T-21-19 Radios Switching Between OPS 2 & 3 Blue Line T- 21-25 SOP 34A Malfunctioning Class 2 Rail Vehicles Inspection Location Main Track Yard Station OCC RTA Facility Office X X X Line(s) & Track Number Microsoft Meeting Chain Marker and/or Station(s) NA			Reference			
Verification Rev 3 T-21-15 Crew Support T-21-12 Green Line ACS T- 21-14 Green Line TPSS/TBS T-21- 21 Remove Operating Rule 3.16 T- 21-22 Storage Class 1 Rail Vehicles T-21-24 Fire and Smoke T-21-19 Radios Switching Between OPS 2 & 3 Blue Line T- 21-25 SOP 34A Malfunctioning Class 2 Rail Vehicles		NA				
Inspection Location Track Tr						
Line(s) & Track Number Microsoft Meeting Chain Marker and/or Station(s) NA	Tunnel	Elevated	I N/A			
Number Microsoft Meeting Chain Marker and/or Station(s) NA			Х			
	110					
Head Car Number Number of Cars						
Vehicles NA NA Equipment NA						
The WMSC Inspector attended a meeting of the rules committee. In attendance were Number of Defects						
senior management representatives from various departments. Due to COVID-19 and social distancing, this inspection was completed utilizing Microsoft Meeting to minimize Recommended Finding?	Recommended Finding?		No			
	Remedial Action Required?		No			
Vote i. T-21-24 Fire and Smoke c. Approved i. T-21-19 Radios Switching Between OPS 2 & 3 Blue Line ii. T-21-25 SOP 34A Malfunctioning Class 2 Rail Vehicles 6. ROCC/DOC UPDATE a.	existing and pending new rules. The meeting agenda items were: 1. CALL TO ORDER 2. SAFETY CONTACT 3. APPROVAL OF MINUTES (05/05/21) 4. Temporary Orders a. Ready to Vote i. T-20-31 Power Energization Verification Rev 3 b. Approved i. T-21-15 Crew Support ii. T- 21-12 Green Line ACS iii. T-21-14 Green Line TPSS/TBS 5. Permanent Order a. Proposed i. T- 21-21 Remove Operating Rule 3.16 ii. T-21-22 Storage Class 1 Rail Vehicles b. Ready to Vote i. T-21-24 Fire and Smoke c. Approved i. T-21-19 Radios Switching Between OPS 2 & 3					
Remedial Action						

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date		
		2021/05/19		
Inspector in Charge's Name	Inspection Team			

Form WMSC-IR-1 Version date: 1/11/2022



Inspection Form

Washington Metrorail Safety Commission

LeBon Bruce Walker Richard David

Form WMSC-IR-1 Version date: 1/11/2022

Form WMSC-IR-1