

## **Inspection Form**

### Form WMSC-IR-1

## Washington Metrorail Safety Commission

### **Agency/Department Information**

Increation Date	YYYY	MM	DD	Papart Number	20101121 \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\					
Inspection Date	2019	11	21	Report Number	20191121-WMATA-KEK-8					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	WMATA – ATC	Sub- Department		ATC		
	ı	Name		Email	Office Phone		Mobile Phone			
Rail Agency Department Contact Information										
Inspection Location	K98 – K & N Junction – Orange & Silver Lines									

### **Inspection Summary**

Inspection Activity #	1	2	3	4	5	6
Activity Code	STC-OBS-RM					
Inspection Units	1 – Control Room					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	0					
Remedial Action Required <sup>1</sup>	NO					
Recommended Reinspection	NO					

### **Activity Summaries**

Inspection Activity #	2 I	nspection Sul	bject	Cab Transmit & Track Circuit 1			uit Testing	Activity Code		ST	С	OBS	TM	
Job Briefing Employee Name/Title	WMATA RWIC – No Briefing performed. Inspection of TCR			•		mpanied ector?	YES	Out Brief Conducted	YES	Time	1245	am	Outside Shift	NO
Related Reports	N/A			Related CAPS / Findings N/A										
	Ref Rule			Rule or S	e or SOP		Standard		Other / Title			Checklist Reference		
Related Rules, SOPs, Standards, or Other	RWP													
Standards, or other	WMATA	MATA ATC-1000 ATC-100		ATC-100	000									
Inspection Location	Main Track	Yard	Stat	ion (	occ	RTA Facility	WMSC Office		At-grade Tunnel		Elevated		N/A	
						TCR		Track Type						
line(a)	ne(s)  K & N-Line  Track Number  Chain Marker and/or Station(s)  K98 (K8			From			То							
Line(s)			er		and/or St		ation(s)	K98 (K&N Junction) +/-			K98 (I	(98 (K&N Junction) +/-		
	Head Car Number			Number of Cars										
Vehicles	N/A			N/A		Equipment		N/A						
Description	WO#15384987 Number of Defects 0						0							

<sup>&</sup>lt;sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
KEMMERY E. KENDRICK		11-21-19
Inspector in Charge – Name	Inspection Team	
KEMMERY E. KENDRICK	WASHINGTON METRORAIL SAFETY COMMISSION	

Form WMSC-IR-1 Version date: 10/5/18



# **Inspection Form**

## Form WMSC-IR-1

# Washington Metrorail Safety Commission

	WMSC personnel under the protection of a WMATA RWIC, West Falls Church TCR	Recommended Finding?	NO
	Inspection was performed. The location: TCR K98 +/- (K & N Junction) Train Control Room West Falls Church. Crew members proceeded working inspection	Remedial Action Required?	NO
	the room using a checklist. Work commenced at 1254 and ended at K98 TCR location approximately 1300hrs.  No notable deficiencies noted:	Recommended Reinspection?	NO
Remedial Action			

Photos:...

Form WMSC-IR-1 Version date: 10/5/18