

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	201012045 WAATA KEK 11				
	2019	12	04	Report Number	201912045-WMATA-KEK-11				
Rail Agency Name	Washington Metropolitan Area Transi Authority			Rail Agency Department	WMATA - ATC	Sub- Department AT		ATC-PMI	
		G		Email	Office Phone		Mobile Phone		
Rail Agency Department Contact Information									
								– C-7 to J03	
Inspection Location	C08 – C01-270+00 to 307+58 – Pentagon to Pentagon City – Blue & Yellow Line								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	STC-OBS-RM					
Inspection Units	Various					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	0					
Remedial Action Required ¹	NO					
Recommended Reinspection	NO					

Activity Summaries

Inspection Activity #	1	Inspect	tion Subj	ject	Wayside Inspection					Activity Code		ST	С	OBS	WI
Job Briefing Employee Name/Title	WMATA RWIC –			Accom Inspec	panied tor?	YES	Out Brief Conducted	YES	Time	1009	am	Outside Shift	NO		
Related Reports	N/A				Related CAPS / Findings N/A										
	Ref Rule or			Rule or S	SOP Standard				Other / Title			Checklist Reference			
Related Rules, SOPs, Standards, or Other	RWP - AMF						APTA	Book of Pla		Plans	s Fo		Form 3004		
Standards, or Other	ATC-3	004			3004			RT-RP-SC-0	033-03						
Inspection Location	Mair Trac		Yard Stat		on C	осс	RTA Facility	WMSC Office	-	At-grade	At-grade Tunnel		Elevated		N/A
	x			х					Track Type			x			
1:	Blu & YL Track Number			Trad #4		Chain Marker		From			То				
Line(s)			er	Track #	·1 i	and/or Station(s)		CM C08 (Pentagon City) 270 +00			CM C07 (Pentagon) 370+00				
Vehicles	Hea	d Car Ni	umber	1	Number of Cars Equip			Equipment N/A							
		N/A													

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
KEMMERY E. KENDRICK		12.04.2019
Inspector in Charge – Name	Inspection Team	
KEMMERY E. KENDRICK	Washington Metrorail Safety Commission	



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	ACT-PMI Wayside Inspection, December 4, 2019. Between C1-270+00 Pentagon	Number of Defects	#
	C07 to C1 307+00 Pentagon City C08. ATC work crew under the direction of RWIC, using AMF, working under normal revenue service, in conjunction with 10mph	Recommended Finding?	NO
	speed restrictions; performed regular PMI Wayside Inspection in conjunction with	Remedial Action Required?	NO
Description	the High Frequency Track Circuit Verification Testing. After the Job Safety Briefing the roadway crew members were transported by train to $CM - C1-270+00$ to perform the required quarterly ATC Wayside Inspection on Track #1 at approximately 0109. With Form 3004 in hand the ATC roadway crew working from $CM - C1-270+00$, proceeding East $CM - C1$ 70+00 began inspecting the route; assuring that the right-of-way is free of defects that can result in failures. The inspection includes checking all platform areas, appropriate signage, ballast, rails, impedance bond connections, ATO markers, and junction boxes for any visible anomalies. No deficiencies to note	Recommended Reinspection?	NO
Remedial Action			

Photos: