



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200715-WMSC-RRD-1		
	2020	06	15				
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	SAFE	Sub- Department	Fire Marshal's Office
Rail Agency Department Contact Information	Name		Email	Office Phone		Mobile Phone	
	██████████ ██████████		██████████ ██████████	██████████ ██████████		██████████ ██████████	
Inspection Location	West Falls Church Yard Operations Building (K92)						

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	SAFE-GEN-RR	SAFE-GEN-RR	SAFE-GEN-RR	SAFEGEN-RR	SAFE-GEN-RR	SAFE-GEN-RR
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	2					
Recommended Finding	No					
Remedial Action Required¹	Yes					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1	Inspection Subject	Complete Inspection				Activity Code		SAFE	GEN	RR
Job Briefing Employee Name/Title	N/A		Accompanied Inspector?	No	Out Brief Conducted	No	Time	N/A	Outside Shift	No	
Related Reports			Related CAPS / Findings								
Related Rules, SOPs, Standards, or Other	Ref	Rule or SOP		Standard		Other / Title		Checklist Reference			
	VA. State Fire Prevention Code			NFPA 130, 5.3.11		VSFPC					
				See sub-sections below							
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
			X								
Line(s)	N/A	Track Number	N/a	Chain Marker and/or Station(s)	From			To			
					West Falls Church Operations Bldg			West Falls Church Operations Bldg			

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature RRD.		Date 7/15/2020
Inspector in Charge – Name Richard R. David	Inspection Team RRD WMSC	



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Vehicles	Head Car Number	Number of Cars			
	N/A	N/A	Equipment	# 1 and 2 Lighting	
Description	<p><i>This inspection was done virtually. Complete inspection of West Falls Church Operations Building. This report was conducted by WMATA's SAFE Fire Marshal's office and forwarded to WMSC for documentation due to Covid 19 social distancing. I concur with the inspection and remedial actions. Per the FM reinspection date July 15, 2020.</i></p> <p>1. Item Found: Exit Light Inoperable Location: Front Door of Building Deficiency: VSFPC 1011.6.2 - Exit Sign Illumination Corrective Action: Exit sign must always be illuminated Assigned to: PLNT Work Order #: 15743762 Date opened: June 15, 2020 Date closed: Open at this time Follow Up Inspection Date: July 15, 2020.</p> <p>2. Item Found: Exit Light Inoperable Location: Rear Door of Building Deficiency: VSFPC 1011.6.2 - Exit Sign Illumination Corrective Action: Exit sign must always be illuminated Assigned to: PLNT Work Order 15743762 Date open: June 15, 2020 Date close: Open at this time Follow Up Inspection Date: July 15, 202</p>			Number of Defects	2
				Recommended Finding?	No
				Remedial Action Required?	Yes
				Recommended Reinspection?	Yes
Remedial Action	As listed above				

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections

Inspector in Charge – Signature RRD.		Date 7/15/20
Inspector in Charge – Name Richard R. David	Inspection Team RRD WMSC	

Photos:

0