

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20202006 W/N	40T0 I	NA\A/ 1		
	2020	06	30	Report Number	20203006-WMATA-JMW-1				
Rail Agency Name	Washington Metropolitan Area Tra Authority			Rail Agency Department	Operations	Sub- Department		TRST	
		Name		Email	Office Phone			Mobile Phone	
Rail Agency Department Contact Information									
Inspection Location	Washington Union Station								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TRK-OPS-GEN					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	NO					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summaries

Inspection Activity #	1	1 Inspection Subject Radio M			Monito	Ionitoring Observation/Inspection				Activity Code		K	OPS	GEN	
Job Briefing Employee Name/Title	N/A					mpanied ector?	N/A	Out Brief Conducted	N/A	Time	110	00	Outside Shift	N/A	
Related Reports	N/A				Related CAPS / Findings Proper Radio			Protocol	Protocol						
	Ref Rule or S			SOP	OP Standard			Other / Title			Checklist Reference				
Related Rules, SOPs,	N/A														
Standards, or Other															
Inspection Location	Mai Trac	· ·	Yard	Stat	tion OCC		RTA Facility	WMSC Office	Track Type	At-grade	At-grade Tunnel		Elevated		N/A
									паск туре						
Line(s)	Track			N/A		Chain Marker			From		То				
Line(s)	A/B Number N,		IN/A	and/or Station(s)			N/A	N/A				i			
Vehicles	Head Car Number				Numbe	r of Cars									
venicles					Equip			ment	int						
											Number of Defects NO				NO
Description											Recommended Finding?				NO
											Remedial Action Required?				NO

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	The WMSC Inspector conducted a radio inspection of Metrorail operations on OPS 1. Currently, with COVID-19 social distancing measures in place, there's minimum physical interaction with Metrorail employees. Observations during radio inspection:		
	 1. 1214 ROCC announcements or track personnel on the roadway 2. Track Unit 6165 called three times with no response (dead spot) 3. Track Unit 6321 with 6331 (AMF) and 6140 performing a track inspection on Track #1. 	Recommended Reinspection?	NO
Remedial Action	N/A		
Effective Practices	N/A		

Inspector in Charge - Signature		Date
		06/30/20
Inspector in Charge – Name	Inspection Team	
Jemayne Walker		

Form WMSC-IR-1 Version date: 10/5/18

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.