



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200828-WMSC-RRD-1		
	2020	08	03				
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	SAFE	Sub- Department	Fire Marshal's Office
Rail Agency Department Contact Information	Name		Email	Office Phone		Mobile Phone	
	██████████ ██████████		██████████ ██████████	██████████ ██████████		██████████ ██████████	
Inspection Location	F99 Branch Ave Rail Yard Building E. 5700 Capitol Gateway Drive, Camp Springs MD 20746						

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	EMGT-GEN-RR					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required¹	No					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1	Inspection Subject	Complete inspection				Activity Code		SAFE	GEN	RR
Job Briefing Employee Name/Title	N/A		Accompanied Inspector?	No	Out Brief Conducted	No	Time	N/A	Outside Shift	No	
Related Reports			Related CAPS / Findings								
Related Rules, SOPs, Standards, or Other	Ref		Rule or SOP		Standard		Other / Title		Checklist Reference		
	Department of Permitting Inspection Enforcement. (PG)				NFPA & DPIE		Fire Marshal's Directive				
					See sub sections below						
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
					X			X			
Line(s)	N/A		Track Number	N/A		Chain Marker and/or Station(s)	From		To		
							F99 Operations Building E		F99 Operation Building E		

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature RRD.	Date 8/28/2020
Inspector in Charge – Name Richard R. David	Inspection Team RRD WMSC



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

					F99 Operations Building E	
Vehicles	Head Car Number	Number of Cars		Equipment		
	N/A	N/A				
Description	<p><i>Due to Covid 19 social distancing, this inspection was done virtually. I concur with the complete inspection of F99 Branch Ave Rail Yard Building E. Follow up inspection date is September 04, 2020 to have defect corrected.</i></p> <p>1. Item Found: Fire lane signs are faded Location: Rear of Building E Code Reference: DPIC Fire Municode Subtitle Corrective Action: Replaced old faded signs with new signage Assigned To: PLNT sign shop Work Order #: Pending Date Opened: Aug 4, 2020 Date Closed: Open Follow-Up Inspection Date: September 4, 2020</p> <p>2. Item Found: Fire alarm annunciator showing trouble condition Location: 1st floor lobby Code Reference: NFPA 1, 2015, Section 4.5.8.1. Corrective Action: Correct the issue causing no power to panel # 8. Assigned To: COMM Work Order: Pending Date Opened: Aug 4, 2020 Date Closed: Open Follow-Up Inspection Date: September 4, 2020</p> <p>3. Item Found: FDC Signage Not Found Location: Front Exterior face of the building Code Reference: Fire Marshal's Directive, NFPA 13 Corrective Action: Upgrade signage Assigned To: PLNT Sign Shop Work Order: Pending Date Opened: Aug 4, 2020 Date Closed: Open Follow-Up Inspection Date: September 4, 2020</p> <p>4. Item Found: Fire Extinguisher is not current on monthly inspection Location: Rear of the building, Room # 102 Code Reference: NFPA 101, 2015 Section 9.6.1.4 Corrective Action: Perform monthly inspection and document on the tag Assigned To: PLNT Work Order: Pending Date Opened: Aug 4, 2020 Date Closed: Open Follow-Up Inspection Date: September 4, 2020</p>				Number of Defects	4
					Recommended Finding?	No
					Remedial Action Required?	No
					Recommended Reinspection?	No
Remedial Action	As noted					

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections

Inspector in Charge – Signature RRD.		Date 08/28/2020
Inspector in Charge – Name Richard R. David	Inspection Team RRD WMSC	