

# **Inspection Form**

### Form WMSC-IR-1

# Washington Metrorail Safety Commission

#### Agency/Department Information

| Inspection Date                               | YYYY   | MM | DD | Report Number             | 20201007-WMATA-TKS-1 |                      |              |  |  |
|---|--|----|----|---------------------------|----------------------|----------------------|--------------|--|--|
| inspection Date                               | 2020   | 10 | 07 | Report Number             |                      |                      |              |  |  |
| Rail Agency Name                              | Washington Metropolitan Area Transit<br>Authority          |    |    | Rail Agency<br>Department | TRPM                 | TRPM Sub- Department |              |  |  |
| D-:  A  | Name   |    |    | Email                     | Office Phone         |                      | Mobile Phone |  |  |
| Rail Agency Department<br>Contact Information |  |    |    |                           |                      |                      |              |  |  |
| Inspection Location                           | C-Line, King Street (C13) Tie-Breaker Station, King Street |    |    |                           |                      |                      |              |  |  |

#### Inspection Summary

| Inspection Activity #                 | 1          | 2 | 3 | 4 | 5 | 6 |
|---------------------------------------|------------|---|---|---|---|---|
| Activity Code                         | TP-GEN-OBS |   |   |   |   |   |
| Inspection Units                      | 1          |   |   |   |   |   |
| Inspection Subunits                   | 1          |   |   |   |   |   |
| Defects (Number)                      | 0          |   |   |   |   |   |
| Recommended Finding                   | No         |   |   |   |   |   |
| Remedial Action Required <sup>1</sup> | No         |   |   |   |   |   |
| Recommended Reinspection              | No         |   |   |   |   |   |

#### **Activity Summary**

| Inspection Activity #                       | 1  | Inspection Sub  | ject     | Virtual I   | nspect                      | tion – TBS Vi   | sual Inspect   | ion                    | Activity Code |        | TP                    | GE       | N                   | OBS |
|---|--|---|----------|-------------|-----------------------------|-----------------|----------------|------------------------|---------------|--------|-----------------------|----------|---------------------|-----|
| Job Briefing<br>Employee<br>Name/Title      | WMATA TRPM Personnel   |   |          |             | Accompanied Inspector?      |                 | N/A            | Out Brief<br>Conducted | N/A           | Time   | 1000<br>140           |          |                     | No  |
| Related Reports                             | N/A  | N/A   |          |             | Related CAPS / Findings N/A |                 |                |                        |               |        | •                     |          |                     |     |
|   | Ref  |   |          | Rule or SOP |                             |                 | Standard       | dard Other / 1         |               |        | itle Ch               |          | Checklist Reference |     |
| Related Rules, SOPs,<br>Standards, or Other | INSPECTOR AC UNITAL ACTION TRACTION TO THE SUBSTATAL TO THE SUBSTATAL TABLE TO THE SUBSTATAL TABLE TO THE SUBSTATAL TABLE TO THE SUBSTATAL TABLE TO THE SUBSTAL TABLE TA | ENANCE<br>TION<br>COR DC<br>RICAL FACILITIE<br>IT SUBSTATION<br>ARY ELECTRICA | IS<br>IL |             |                             |                 |                |                        |               |        |                       |          |                     |     |
|   | MSRPH  | I   |          |             |                             |                 |                |                        |               |        |                       |          |                     |     |
| la annuali an la anti                       | Main<br>Track  | I Vard  | Stati    | on C        | осс                         | RTA<br>Facility | WMSC<br>Office | Track Type             | At-grade      | e Tu   | nnel                  | Elevated |                     | N/A |
| Inspection Location                         |  |   | X        |             |                             |                 |                |                        | х             |        |                       |          |                     |     |
| Line(s)                                     | A-Line Track   |   |          | N/A         |                             | Chain Marker    |                | From                   |               | •      | То                    |          |                     |     |
| Line(s)                                     | A-LINE   | Number  |          | 14/ /       | and/or Stat                 |                 | ation(s)       | King Street TBS (C13)  |               | King S | King Street TBS (C13) |          |                     |     |

Form WMSC-IR-1 Version date: 10/5/1

Version date: 10/5/18



## **Inspection Form**

### Form WMSC-IR-1

## Washington Metrorail Safety Commission

|                 | Head Car Number                 | Number of Cars   |                           |                           |     |  |  |  |  |
|-----------------|---------------------------------|--|---------------------------|---------------------------|-----|--|--|--|--|
| Vehicles        | N/A                             | N/A  | Equipment                 | N/A                       | N/A |  |  |  |  |
|                 |                                 | rmed a virtual inspection  | Number of Defects         | 0                         |     |  |  |  |  |
|                 | Traction Power Mainte           | nance's (TRPM) job safe  | Recommended Finding?      | No                        |     |  |  |  |  |
|                 | The WMSC inspector of           | lid not note any defects   | Remedial Action Required? | No                        |     |  |  |  |  |
| Description     | Room Inspection PMI of by TRPM. | rmed a virtual inspection<br>conducted at King Street<br>lid not note any defects. | TBS (C13) via test sh     | Recommended Reinspection? | No  |  |  |  |  |
| Remedial Action | N/A                             |  |                           |                           |     |  |  |  |  |

<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

| are sufficient and effective.   |                 |      |
|---------------------------------|-----------------|------|
| Inspector in Charge - Signature |                 | Date |
|                                 |                 |      |
| Inspector in Charge – Name      | Inspection Team | •    |
| Tino Sahoo                      | Tino Sahoo      |      |
|                                 |                 |      |

Form WMSC-IR-1 Version date: 10/5/18