



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20201103-WMSC-RRD-1	
	2020	10	15			
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	WMATA-SAFE	Sub- Department Fire marshal
Rail Agency Department Contact Information	Name		Email	Office Phone		Mobile Phone
	██████████ ██████████		██████████ ██████████	██████████ ██████████		██████████ ██████████
Inspection Location	D12 - Landover Station 3000 Pennsy Drive, Hyattsville, Md 20785					

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	SAFE-GEN-RR					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	2					
Recommended Finding	No					
Remedial Action Required¹	Yes					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1	Inspection Subject	Landover Station				Activity Code	SAFE	GEN	RR	
Job Briefing Employee Name/Title	N/A		Accompanied Inspector?	No	Out Brief Conducted	No	Time	N/A	Outside Shift	No	
Related Reports			Related CAPS / Findings								
Related Rules, SOPs, Standards, or Other	Ref		Rule or SOP		Standard		Other / Title		Checklist Reference		
	International Fire Code				NFPA, IFC						
					See sub sections below						
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
			X					X			
Line(s)	N/A		Track Number	N/A		Chain Marker and/or Station(s)	From		To		
							Station limits		Station limits		

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature RRD.	Date 11/03/2020
Inspector in Charge – Name Richard R. David	Inspection Team RRD WMSC



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Vehicles	Head Car Number	Number of Cars	Equipment	#2.FAAP showing a fire alarm trouble condition	
	N/A	N/A			
Description	<p><i>Due to Covid 19 social distancing, this inspection was done virtually. I concur with the finding of the complete station inspection. Items assigned to the appropriate departments and should be corrected by the re-inspection date 11/28/20.</i></p> <p><i>1. Item Found: Missing fire department connection signage Location: In front of Station, west side - Standpipe Code Reference: IFC 912.5 Corrective Action: Upgrade signage Assigned To: PLNT Graphics Work Order #: 15962486 Date Opened: 10/28/2020 Date Closed: Open Follow-up Inspection Date: 11/28/2020</i></p> <p><i>2. Item Found: Fire alarm panel showing trouble Location: Kiosk Code Reference: IFC 906.2 Corrective Action: Correct issue that is causing the trouble Assigned To: COMM Work Order #: 15962479 Date Opened: 10/28/2020 Date Closed: Open Follow-up Inspection Date: 11/28/2020</i></p>			Number of Defects	2
				Recommended Finding?	No
				Remedial Action Required?	Yes
				Recommended Reinspection?	Yes
Remedial Action	None				

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections

Inspector in Charge – Signature RRD.		Date 11/03/2020
Inspector in Charge – Name Richard R. David	Inspection Team RRD WMSC	

Photos: