

Inspection Form

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date		YYYY/MM/DD 2021/06/21	Report Number	20210621-WMSC-RRD-2				
Rail Agency Name	Wash	ington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	SAFE		Contact Information					
Inspection Location	F10	Suitland Station						
Inspection Summary								
Inspection Activity #		1						
Activity Code		SAFE-GEN-RR						
Inspection Units		1						
Inspection Subunits		0						
Defects (Number)		2						
Recommended Finding		No						
Remedial Action Required ¹		No						
Recommended Reinspection		Yes						

Activity Summaries

Inspection Activity #	1 Inspection Sub			ect Suitland Station inspection				Activity Code			SAFE-GEN-RR				
Job Briefing Employee Name/Title	N/A			Accompanied Inspector?			No	Out Brief Conducted	No	D Time				Outside Shift	No
Related Reports	Annual Station inspections. Station Re-inspections			Related CAPS / Findings				N/A							
Related Rules,	Ref		Rule	le or SOP			Standard		Other / Title				Checklist Reference		
SOPs, Standards, or Other	NFPA & IFC														
Inspection Location	Main Track	Yard	Station	OCC	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunne		el Eleva		ted I	N/A	
			Х						Х						
Line(s) & Track Number	F10 Suitland Station				Chain Marker and/or Station(s)			From				То			
Nulliper					<u> </u>	1		Station Limits	Station Limits Station Li				n Limit	limits	
Vehicles	Head Car	Number	N	Number of Cars		Equipment Fire/Life safety		v equipme	ent						
	N,	/Α		N/A				.,	·/ · · · ·						
Description	This record review of the station reinspection shows 2 deficiencies out of 5 found in the									Number of Defects					
	initial inspection. The deficiencies have been assigned to the appropriate department with work orders and has a follow up date of 7/10/21.								Recommended Finding?					No	J
Description									Remedial Action Required?					No	
								Recommended Reinspection?					Yes		
Remedial Action															

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2021/06/21
Inspector in Charge's Name Richard David	Inspection Team N/A	