



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD 2021/07/07	Report Number	20210704-WMATA-KEK-24
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	Rail Operations Control Center	Contact Information	
Inspection Location	Blue Line - D01 - Federal Triangle Station		

Inspection Summary

Inspection Activity #	1
Activity Code	1
Inspection Units	1
Inspection Subunits	1
Defects (Number)	0
Recommended Finding	No
Remedial Action Required¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity #	1	Inspection Subject	1				Activity Code	1			
Job Briefing Employee Name/Title	N/A	Accompanied Inspector?	No	Out Brief Conducted	No	Time	10:34 PM	Outside Shift			
Related Reports	N/A	Related CAPS / Findings			N/A						
Related Rules, SOPs, Standards, or Other	Ref	Rule or SOP			Standard		Other / Title		Checklist Reference		
	MSRPH										
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
	X										
Line(s) & Track Number	Blue Line - D01 - Federal Triangle Station			Chain Marker and/or Station(s)		From		To			
						CM: 13 + 36		CM: 19 + 36			
Vehicles	Head Car Number		Number of Cars		Equipment		Radio - Open MHz Communications				
	N/A		N/A								
Description	Holiday radio monitoring coverage. Ops #2, ROCC/RTRA. July 4, 2021 10:34pm – Federal Triangle, track #2, station supervisor reported that a customer fell or entered the roadway. 10:35pm – station supervisor reported Track #2 clear and the customer returned to platform. All radio transmission were clear and concise. Communications clearly transmitted and received as prescribed per MSRPH rules.						Number of Defects		0		
							Recommended Finding?		No		
							Remedial Action Required?		No		
							Recommended Reinspection?		No		
Remedial Action											

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature	Date 2021/07/07
Inspector in Charge's Name Kemmerly Kendrick	Inspection Team N/A