



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD 2021/09/03	Report Number	20210903-WMSC-RRD-2
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	SAFE	Contact Information	
Inspection Location	Foggy Bottom GWU Station		

Inspection Summary

Inspection Activity #	1
Activity Code	SAFE-GEN-RR
Inspection Units	1
Inspection Subunits	0
Defects (Number)	36
Recommended Finding	No
Remedial Action Required¹	No
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Inspection Subject	Foggy Bottom-GWU Station				Activity Code	SAFE-GEN-RR			
Job Briefing Employee Name/Title	N/A	Accompanied Inspector?		Out Brief Conducted		Time		Outside Shift	No		
Related Reports	Previous station inspections annual. Previous follow-up inspections.		Related CAPS / Findings								
Related Rules, SOPs, Standards, or Other	Ref	Rule or SOP			Standard		Other / Title		Checklist Reference		
	NFPA and IFC										
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
			X								X
Line(s) & Track Number	Foggy Bottom GWU Station			Chain Marker and/or Station(s)			From		To		
							Station limits		Station limits		
Vehicles	Head Car Number		Number of Cars		Equipment		Fire/life safety equipment and assets.				
	N/A		N/A								
Description	Foggy Bottom complete station inspection report attached.						Number of Defects		36		
							Recommended Finding?		No		
							Remedial Action Required?		No		
							Recommended Reinspection?		Yes		
Remedial Action											

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature	Date 2021/09/03
Inspector in Charge's Name Richard David	Inspection Team N/A