

## **Inspection Form**

Form WMSC-IR-1

Washington Metrorail Safety Commission

## Agency/Department Information

Insurantian Data	YYYY/MM/DD	Report Number	20211002 WMSC DDD 2			
Inspection Date	2021/10/03	Report Number	20211003-WMSC-RRD-2			
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name			
Rail Agency Department	SAFE	Contact Information				
Inspection Location	Rail Operation Control Center					

## **Inspection Summary**

Inspection Activity #	1
Activity Code	SAFE-GEN-OBS
Inspection Units	1
Inspection Subunits	2
Defects (Number)	0
Recommended Finding	No
Remedial Action Required <sup>1</sup>	No
Recommended Reinspection	Yes

## **Activity Summaries**

Inspection Activity #	1	Ins	spection Sul	n Subject ROCC/IMO/WMSC's CCTV ac			's CCTV acces	Activity Code				SAFE-GEN-OBS			
Job Briefing Employee Name/Title	N/A			Accompanied Inspector?		No	Out Brief Conducted	No	No Time		Outside Shift		N O		
Related Reports				Related CAPS / Findings				•	•						
Related Rules,	Ref			ule or SOP			Standard		Other / Title			Chec	Checklist Reference		
SOPs, Standards, or Other			SOF	? 1A											
Inspection Location	Main Track	Yard	Station	ОСС	RTA F	acility	WMSC Office	Track Type	At-grade Tur		Tunne	el Ele	Elevated N/A		
			Х												
Line(s) & Track Number	Rail Operation Control Center Chain Marker an			rker and/	or Station(s)	From N/A					То				
Vehicles	Head Car	Number		Number of Cars				WMSC's CCTV	access. ROCC's Fire Liaison, IMO, and Rail 1 CCTV's and						
	N/	/A		Equipmen			ent	radio's.							
Description.	On September 20, 2021 the WMSC inspector visited the ROCC to check CCTV access and to								Number of Defects					0	
	observe the FL/IMO/Rail 1. The CCTV work as designed after access was granted by IT. No issues.								Recommended Finding?					No	
Description									Remedial Action Required?					No	
	Recommended Reinspec						spection?			Yes					
Remedial Action															

1 The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Action. Closeout of Nemedial Actions may also	be subject to onyoning wivisc verification inspections to ensure corrections are sufficient and effective.	
Inspector in Charge's Signature		Date 2021/10/03
Inspector in Charge's Name Richard David	Inspection Team N/A	

Form WMSC-IR-1 Version date: 1/17/2022