

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Report Number	20211018-WMSC-RRD-1				
Inspection Date	2021/10/18	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	SAFE	Contact Information					
Inspection Location	C09 - Crystal City Station 1750 South Clark Street Arlington, VA						

Inspection Summary

Inspection Activity #	1
Activity Code	SAFE-GEN-RR
Inspection Units	1
Inspection Subunits	0
Defects (Number)	36
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	li	nspection Su	bject	C09 - Crys	stal City S	tation	action Activity Code					SAFE-GEN-RR			
Job Briefing Employee Name/Title	N/A			Accompanied Inspector?			No	Out Brief Conducted	No	No Time				Outside Shift	No	
Related Reports	Previous sta Previous sta			Related CAPS / Findings				•	•		•	*		•		
Related Rules,	Ref Ru			le or SOP			Standard		Other / Title				Checklist Reference			
SOPs, Standards, or Other	NFPA IFC															
Inspection Location	Main Track	Yard	Statio	OCC	RTA Facility		WMSC Office	Track Type	At-grade Tunne		el Elevated		ted	N/A		
			Х											Χ		
Line(s) & Track Number	C09 - Crystal City Station 1750 South Clark Street Arlington, VA Chain Marker and/or Station(s)				From Station limits Stati					To ion limits						
	Head Car Number N			Number of Cars												
Vehicles	N/A			N/A Equipm			ent	Fire Life Safet	ty assets.							
Description	Record review of Station C09 Crystal City Station Inspection report attached.								Number of Defects					36		
										Recommended Finding?				No	No	
										Remedial Action Required?				No		
									Recommended Reinspection?				Yes			
Remedial Action			·		·											

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to angoing WMSC verification inspections to ensure corrections are sufficient and effective.

Action. Closeout of Remedian Actions may also be subject to ongoing winst verification inspections to ensure corrections are sufficient and effective.						
Inspector in Charge's Signature	Date 2021/10/18					
Inspector in Charge's Name Richard David	Inspection Team N/A					

Form WMSC-IR-1 Version date: 1/17/2022