



## Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

**Agency/Department Information**

<b>Inspection Date</b>	YYYY/MM/DD 2021/10/21	<b>Report Number</b>	20211021-WMSC-RRD-1
<b>Rail Agency Name</b>	Washington Metropolitan Area Transit Authority	<b>Rail Agency Department</b>	Name
<b>Rail Agency Department</b>	SAFE	<b>Contact Information</b>	
<b>Inspection Location</b>	Largo Rail Division Facility/G98 9450 Lottsford Road, Upper Marlboro MD		

**Inspection Summary**

<b>Inspection Activity #</b>	1
<b>Activity Code</b>	SAFE-GEN-RR
<b>Inspection Units</b>	1
<b>Inspection Subunits</b>	0
<b>Defects (Number)</b>	7
<b>Recommended Finding</b>	No
<b>Remedial Action Required<sup>1</sup></b>	
<b>Recommended Reinspection</b>	Yes

**Activity Summaries**

<b>Inspection Activity #</b>	1	<b>Inspection Subject</b>	Largo Rail Division Facility/G98				<b>Activity Code</b>	SAFE-GEN-RR			
<b>Job Briefing Employee Name/Title</b>	N/A	<b>Accompanied Inspector?</b>	No	<b>Out Brief Conducted</b>	No	<b>Time</b>		<b>Outside Shift</b>	No		
<b>Related Reports</b>	Previous inspections. Previous Re-inspections.		<b>Related CAPS / Findings</b>								
<b>Related Rules, SOPs, Standards, or Other</b>	<b>Ref</b>	<b>Rule or SOP</b>			<b>Standard</b>		<b>Other / Title</b>			<b>Checklist Reference</b>	
	NFPA IFC										
<b>Inspection Location</b>	<b>Main Track</b>	<b>Yard</b>	<b>Station</b>	<b>OCC</b>	<b>RTA Facility</b>	<b>WMSC Office</b>	<b>Track Type</b>	<b>At-grade</b>	<b>Tunnel</b>	<b>Elevated</b>	<b>N/A</b>
					X						
<b>Line(s) &amp; Track Number</b>	Largo Rail Division Facility/G98 9450 Lottsford Road, Upper Marlboro MD				<b>Chain Marker and/or Station(s)</b>		<b>From</b>		<b>To</b>		
							N/A				
<b>Vehicles</b>	<b>Head Car Number</b>		<b>Number of Cars</b>		<b>Equipment</b>		Fire Life Safety equipment and assets. Inspection report attached.				
	N/A		N/A								
<b>Description</b>	The WMSC inspector conducted a record review of the Largo Station complete inspection. There are 7 deficiencies. The deficiencies were assigned to the correct department with a follow up date of 10/09/2021.							<b>Number of Defects</b>		7	
								<b>Recommended Finding?</b>		No	
								<b>Remedial Action Required?</b>			
								<b>Recommended Reinspection?</b>		Yes	
<b>Remedial Action</b>											

<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

<b>Inspector in Charge's Signature</b>	<b>Date</b> 2021/10/21
<b>Inspector in Charge's Name</b> Richard David	<b>Inspection Team</b> N/A