

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Report Number	20211101-WMATA-KEK-40			
	2021/11/01	Report Number				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name			
Rail Agency Department	WMATA	Contact Information				
Inspection Location	E10 - Greenbelt Station TCR #207					

Inspection Summary

Inspection Activity #	1
Activity Code	STS/QAI/RR
Inspection Units	6
Inspection Subunits	0
Defects (Number)	0
Recommended Finding	Yes
Remedial Action Required ¹	No
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Ins	pection Sub	Subject Deferred testing follow-up rehab				e to station Activity Code				STS/QAI/RR				
Job Briefing Employee Name/Title	N/A			Accompanied Inspector?			No	Out Brief Conducted	No	Time		11:00 AM		Outside Shift	No	
Related Reports	N/A		Related CAPS / Findings													
Related Rules.	Ref	Rule or SOP Standard Other / Title				Title	Checkli			st Reference						
SOPs, Standards, or Other	ATCM QC Po	licy	ACTI	MCP-Rev 1.0	- 02/17		WMATA-AS	Р	MAXIMO SMS Entry Report							
Inspection Location	Main Track	Yard	Station	occ	RTA Fa	acility	WMSC Office	Track Type	At-gr	grade Tunne		el	Eleva	ted	N/A	
			Х						Х							
Line(s) & Track								From To						o	,	
Number	E10 - Greenl	belt Station	Chain Marker and/or			or Station(s)	532+00					00 - into F99 - Branch ue Yard Suitland				
Vehicles	Head Car Number N			Number of Cars				Maxima CMC D	DEL de company							
venicies	N/	/A		N/A		Equipm	ent	Maximo Sivis R	RFI document							
	ATCM — PM/CM/EEA - Continued maintenance of systems and subsystems must be made to ensure the quality/reliability of such is not compromised. Left unresolved will lead to									Number of Defects)	
			Recommended Finding?				Ye	:S								
	shortened life cycle and reduced asset value to the Authority (pg. 88) FTA-R-2-18-A – requiring WMATA to eliminate Maintenance Order Backlogs to include ATCM. August 20,									Remedial Action Required?				No	o	
Description	2021 - monitored MAXIMO to track ATCS Maintenance Orders for compliance deadlines. Location E10, Greenbelt Station listed as deferred. Station was under construction															
	(Kiewit Corp	o.,) with all	Recommended Reinspection?				Ye	Yes								
	18, 2021, wi															
Remedial Action	marked clos	sed in Max	ımo.													

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective

Action. Closeout of Kemediai Actions may also	be subject to ongoing wivisc verification inspections to ensure corrections are sufficient and effective.	
Inspector in Charge's Signature		Date 2021/11/01
Inspector in Charge's Name Kemmery Kendrick	Inspection Team N/A	

Form WMSC-IR-1 Version date: 1/17/2022