

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information	gency	nt Inform	ation
-------------------------------	-------	-----------	-------

Inspection Date	YYYY/MM/DD	Report Number	20221002-WMATA-KEK-48		
	2022/02/10	Report Number			
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name		
Rail Agency Department	WMATA	Contact Information			
Inspection Location	B11 Glenmont ATCM Field Office Glenmont Yard				

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity #	1	In	spection Su	ıbject	Quarterly Shunt Verification & Weekly Wayside Ins				Activity (
Job Briefing Employee Name/Title	Red Line Su	perintend	ent	Accompanied Inspecto			Yes	Out Brief Conducted	Yes Time			10:00 AM		Outside Shift	No		
Related Reports	Related CAPS / Findings WMSC-19-C000							0 - IIoT Pilot, TOC-ATC-15-005, and FTA-TSR-18-004									
Related Rules,	Ref Rule			ile or SOP	le or SOP				Other / -	Other / Title				Checklist Reference			
SOPs, Standards, or Other	ATC-1000 Re	v 4.0		WMATA ASP, ATC (MCP) Records							Forms 1012A-1 / 1012B-1						
Inspection Location	Main Track	Yard	Statio	n OCC	RTA F	acility	WMSC Office	Track Type	At-grade		Tunnel		At-grade Tunnel El		Eleva	ted	N/A
					>	(
Line(s) & Track		nt ATCM	Field Offic	eld Office Glenmont Chain Marker and/o				From				То					
Number	Yard			CM: 670 +00				CM: 737 + 65				737 + 65					
	Head Car	Number		Number of Cars				Test jumpers, Shunt Straps (hard and soft), Digital Multi									
Vehicles	N/	/A		N/A Equipment			ent	Oscilloscope with isolated inputs: with frequency read-out fund 800/800W card file Extender PCB (US&S part no, N398028), Alstor						,			
	ATCS, PMI Shunt Verification Test & Wayside Inspections									Number of Defects)		
Description									Recommended Finding?				N	0			
Description									Remedial Action Required?					N	0		
	Recommended Reinspection?								N	0							
Remedial Action																	

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial
Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature	Date 2022/02/10		
Inspector in Charge's Name Kemmery Kendrick	Inspection Team		