



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD 2022/02/23	Report Number	20220217_WMSC-RRD-1
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	SAFE	Contact Information	
Inspection Location	West Falls Church Rail Yard S&I Shop 7251 Idylwood Rd. Falls Church VA 22043		

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	4
Recommended Finding	No
Remedial Action Required¹	
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Inspection Subject	West Falls Church Rail Yard S&I Shop				Activity Code				
Job Briefing Employee Name/Title	Inspection Supervisor		Accompanied Inspector?		Yes	Out Brief Conducted	Yes	Time		Outside Shift	No
Related Reports	Previous S&I inspections		Related CAPS / Findings								
Related Rules, SOPs, Standards, or Other	Ref		Rule or SOP			Standard		Other / Title		Checklist Reference	
	NFPA 130 WMATA's Agency Safety Plan										
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
		X									
Line(s) & Track Number	West Falls Church Rail Yard S&I Shop 7251 Idylwood Rd. Falls Church VA 22043				Chain Marker and/or Station(s)		From		To		
							N/A		N/A		
Vehicles	Head Car Number		Number of Cars		Equipment		FLS Assests.				
	N/A		N/A								
Description	WMSC inspector conducted a combined S&I Shop and Fire Life Safety Inspection. Covid 19 protocols were in place. Safety Briefing and sign in was completed prior to the inspection. Shop was clean. Fall protection was set up properly and Blue Flags and accountability tags indicators were in place. Eye wash stations, AED, First Aid and an Emergency Action Plan was present. Fire extinguishers were in compliance. Spill Pallets were in compliance. Chocks and flags in place, rooftop work signage and procedures were visible in the work area. Carwash area: Blue light boxes and signage was good. The shop floor intercom was check and working.							Number of Defects		4	
								Recommended Finding?		No	
								Remedial Action Required?			
								Recommended Reinspection?		Yes	
Remedial Action											

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature	Date 2022/02/23
Inspector in Charge's Name Richard David	Inspection Team Manny Lopez