



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD 2022/03/16	Report Number	
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	OPERATIONS	Contact Information	
Inspection Location	E1 613-50		

Inspection Summary

Inspection Activity #	
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required¹	No
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #		Inspection Subject	Automated Wayside Inspection System (AWIS)			Activity Code					
Job Briefing Employee Name/Title	WMATA/RWIC	Accompanied Inspector?	Yes	Out Brief Conducted	Yes	Time	09:30 AM	Outside Shift	No		
Related Reports	N/A	Related CAPS / Findings			N/A						
Related Rules, SOPs, Standards, or Other	Ref	Rule or SOP			Standard	Other / Title			Checklist Reference		
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
	X							X			
Line(s) & Track Number	E1 613-50				Chain Marker and/or Station(s)			From		To	
								E1 613-50		E1 613-50	
Vehicles	Head Car Number		Number of Cars		Equipment						
	N/A										
Description	The WMSC took part in a WMATA assessment of an AWIS site which will be the location of its first of six AWIS sites. This system will automatically take measurements of wheels on WMATA's railcars and check for defects or deviations. The site inspection was to assess what's needed for each department in terms of work before, after, and during the AWIS installation period.							Number of Defects			
								Recommended Finding?		No	
								Remedial Action Required?		No	
								Recommended Reinspection?		Yes	
Remedial Action											



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Photos:

20220316_105533_lsb_208439_rsb_.jpg



20220316_105341_lsb_208437_rsb_1.jpg





Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

20220316_105347_lsb_208438_rsb.jpg



¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/03/16
Inspector in Charge's Name JeMayne Walker	Inspection Team	