

**Inspection Form** 

## Washington Metrorail Safety Commission

## Agency/Department Information

Inspection Date	-	YYYY/MM/DD 2022/03/25	Report Number	20220324-WMSC-RRD				
Rail Agency Name	Wash	ington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	SAFE		Contact Information					
Inspection Location	Archi	nives to L'Enfant Plaza						
Inspection Summary								
Inspection Activity #		1						
Activity Code								
Inspection Units								
Inspection Subunits								
Defects (Number)		1						
Recommended Finding		No						
Remedial Action Required <sup>1</sup>			No					
Recommended Reinspection		Yes						

## Activity Summaries

Inspection Activity #	1	Ins	pection Sub	n Subject AMF/Rail Ops					Activity Code							
Job Briefing Employee Name/Title	RWIC- OEP 27			Accompanied Inspector?			Yes	Out Brief Conducted	Yes	Time		08:00 AM		Outside Shift	No	
Related Reports	Previous track walk training with emergency personnel.			Related CAPS / Findings				•						-		
Related Rules.	Ref		Rule	Rule or SOP			Standard		Other / Title				Checklist Reference			
SOPs, Standards, or Other	RWP Quick Guide M Handbook			MSRPH RWP												
Inspection Location	Main Track	Yard	Station	OCC	RTA Fa	acility	WMSC Office	Track Type	At-g	ade	Tunnel		Eleva	ted I	N/A	
	Х															
Line(s) & Track Number	Archives to L'Enfant Plaza Chain Marker and/or Station(s) Archives					Archives	From To L'Enfant Plaza									
	Head Car	Number	lumber of Cars			AMF equipment. Gear, flashlight, flag, whistle, lantern, script and radio										
Vehicles	n/a			n/a			lent	3277 @ 0831 A stopped and c	counted for and met compliance. The train lead cars: 3157 @ 0821 AM 77 @ 0831 AM 6090 @ 0840 AM 2004 @ 0852 AM 6010 @ 0901 AM All opped and confirmed with the AMF, adjusted their speed and blew e horn as required.							
			•				reparedness	. ,	Number of Defects					1		
	personnel that were performing a training exercise for 8 regional first responders. There was a total of fourteen personnel walking the roadway between Archives to L'Enfant									Recommended Finding?					D	
	Plaza Stations. The protection utilized for this inspection was Advanced Mobile Flagger									Remedial Action Required?				No		
Description	<ul> <li>(AMF) with the AMF located at L'Enfant Plaza 8-car marker Track #1. The roadway worker in charge (RWIC) was OEP 27, the advanced mobile flagger (AMF) was OEP 22, and the watchman lookout (W/L) was OEP 20. Prior to beginning the inspection activities and track walk, the WMSC inspectors attended a job safety briefing conducted by OEP 27 at Archives Station. The WMSC inspectors contacted the ROCC (rail ops 3) by telephone prior to entering the roadway to brief the inspection activity. An exit briefing was conducted with the Office of Emergency Preparedness RWIC, AMF and W/L at L'Enfant Plaza Station.</li> </ul>								s							
Remedial Action																

<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/03/25
Inspector in Charge's Name	Inspection Team	
Richard David	Bruce Walker Tiffany Minor	