



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD 2022/04/05	Report Number	20220504-WMATA-KEK-51
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	WMATA	Contact Information	
Inspection Location	Carmen Turner Training facility, Building "B"		

Inspection Summary

Inspection Activity #	
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	
Recommended Finding	
Remedial Action Required¹	Yes
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Inspection Subject	0			Activity Code					
Job Briefing Employee Name/Title	ATCM Technical Trainer		Accompanied Inspector?	Yes	Out Brief Conducted	Yes	Time	09:00 AM	Outside Shift	No	
Related Reports	20211214-WMATA-KEK-42		Related CAPS / Findings			WMSC-21-C0113 (Item #2), TOC-ATC-15-013					
Related Rules, SOPs, Standards, or Other	Ref		Rule or SOP		Standard		Other / Title			Checklist Reference	
	20211214-WMATA-KEK-42		WMATA ASP								
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
					X						
Line(s) & Track Number	Carmen Turner Training facility, Building "B"			Chain Marker and/or Station(s)		From			To		
						N/A			N/A		
Vehicles	Head Car Number		Number of Cars		Equipment		E-post wrench, Multi-meters, Schmetics, White Board, and a Projector				
	N/A		N/A								
Description	ATCM Apprentice In-Class and Lab Instruction						Number of Defects			0	
							Recommended Finding?				
							Remedial Action Required?			Yes	
							Recommended Reinspection?			Yes	
Remedial Action											



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Photos:
20220406_140641.jpg



20220406_140734.jpg





Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

20220406_141010.jpg



20220406_141335.jpg






Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

20220406_141631.jpg



¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/04/05
Inspector in Charge's Name Kemmerly Kendrick	Inspection Team N/A	