

## **Inspection Form**

Form WMSC-IR-1

Washington Metrorail Safety Commission

Δσοηςν	/Denar	tmont	Information
Agency	/ Debar	ımenı	miormation

- Against an annual ann								
Inspection Date	YYYY/MM/DD	Report Number	20220414-WMSC-RRD-2					
	2022/04/25	Report Number						
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	SAFE	Contact Information						
Inspection Location	3500 Pennsy Dr. Landover Md. 20785 CTF ROCC							

## **Inspection Summary**

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	1
Recommended Finding	No
Remedial Action Required <sup>1</sup>	Yes
Recommended Reinspection	Yes

## **Activity Summaries**

Inspection Activity #	1	Ins	pection Sub	ject	ROCC/OEP				Activity Code						
Job Briefing Employee Name/Title	N/A	Accompanied Insp			ied Inspecto	or?	No	Out Brief Conducted	No	Time	ie 12:7		20 AM	Outside Shift	Yes
Related Reports				Related CAPS / Findings COO			C0052 C0037 C	C0052 C0037 C0020						•	
Related Rules,	Ref			Rule or SOP			Standard		Other / Title				Checklist Reference		
SOPs, Standards, or Other									NFPA 130						
Inspection Location	Main Track	Yard	Station	occ	RTA Facility		WMSC Office	Track Type	At-grade Tunne		el Elevato		ted	N/A	
				Х											
Line(s) & Track Number	3500 Pennsy Dr. Landover Md. 20785 CTF ROCC Chain Marker and/or Station(s)				N/A	From To N/A									
	Head Car Number Number of Cars														
Vehicles	N/A			N/A Equipme			ent	N/A							
	The WMSC inspector conducted a 3rd shift unannounced inspection of the ROCC. WMSC workstation and CCTV available and working. Information board was up with accurate information.								Number of Defects 1						
5									Recommended Finding?					N	0
Description	iniorniation.							Remedial Action Required?					Yes		
						Recommended Reinspection?				Yes					
Remedial Action	Bring ROCC up to appropriate staffing levels.														

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Action: closeout of hemedian Actions may also be subject to origining wivise verification inspections to ensure corrections are sufficient and effective.						
Inspector in Charge's Signature		Date 2022/04/25				
Inspector in Charge's Name Richard David	Inspection Team N/A					