

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information	gency	nt Inform	ation
-------------------------------	-------	-----------	-------

Insuration Date	YYYY/MM/DD	Report Number	20220405-WMSC-RRD-1			
Inspection Date	2022/04/25	Report Number	20220403-WW3C-NND-1			
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name			
Rail Agency Department	SAFE	Contact Information				
Inspection Location	3500 Pennsy Dr. Landover Md.20785 CTF ROCC					

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Ins	pection Sub	ject	OEP/MAC	/OPS in t	he ROCC		Activity Code						
Job Briefing Employee Name/Title	N/A			Accompanied Inspec			No	Out Brief Conducted	No	Time				Outside Shift	No
Related Reports				Related CA	APS / Findin	gs		C0052 C0037 C0	0020						
Related Rules,	Ref		Rule	ule or SOP			Standard		Other / Title				Checklist Reference		ence
SOPs, Standards, or Other			,			NFPA 130									
Inspection Location	Main Track	Yard	Station	occ	RTA F	acility	WMSC Office	Track Type	At-g	At-grade Tunnel		el	Elevated		N/A
				Х											
Line(s) & Track Number	3500 Pennsy ROCC	Dr. Landov	Chain Marker and/or Station(s) N/A					From	1		N/A	T	0		
Vehicles	Head Car	Number	N	Number of Cars				21/2							
	N/A			N/A Equipme			ent	N/A							
	The WMSC inspector conducted an unannounced observation of the ROCC. WMSC's									Number of Defects				0	
Description	workstation CCTV was operational. MAC/FL/Rail 1,2, and 3 fully staffed. The big board was up with accurate information.								Recommended Finding?				No		
Description	up with accurate information.									Remedial Action Required?				No	
							Recommended Reinspection?					Yes			
Remedial Action															

1 The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Action: closedut of hemedian rections may also be subject to origining withse verification inspections to chaire corrections are sufficient and effective.						
Inspector in Charge's Signature	Date 2022/04/25					
Inspector in Charge's Name Richard David	Inspection Team N/A					