

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information	gency	nt Inform	ation
-------------------------------	-------	-----------	-------

Inspection Date	YYYY/MM/DD	Report Number	20220422-WMSC-RRD-1				
Inspection Date	2022/04/28	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	SAFE	Contact Information					
Inspection Location	C03 - Farragut West Station 900 18TH Street, North West, Washington DC						
Inspection Summary							

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	12
Recommended Finding	Yes
Remedial Action Required ¹	
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Ins	pection Sub	ject	Farragut	West Sta	tion	Activity (
Job Briefing Employee Name/Title	N/A			Accompan	ied Inspecto	or?	No	Out Brief Conducted		Time			Time				Outside Shift	No	
Related Reports		Previous Station inspection 2021/22 FLS Audit report			Related CAPS / Findings				Related CAPS / Findings										
Related Rules,	Ref Rul			ule or SOP			Standard		Other / Title				Checklist Reference		ence				
SOPs, Standards, or Other	NFPA 130 IF	С																	
Inspection Location	Main Track	Yard	Station	occ	RTA F	acility	WMSC Office	Track Type	At-grade		At-grade		At-grade		Tunnel		Elevat	ed 1	N/A
			Х												Χ				
Line(s) & Track Number	CO3 - Farrag Street, Nort				Chain Ma	rker and/	or Station(s)	Station Limits	Sta			on Limits	-						
Vehicles	Head Car	Number	N	Number of Cars			51.5												
	N/	/A		N/A		Equipm	ent FLS assets												
	Annual Station Inspection attached. WMSC inspector concurs with this report . Note there								Number of Defects				12	!					
Description	are items of the FLS assets that are in the fail status.									Recommended Finding?				Ye	s				
Description										Remedial Action Required?									
								Recommended Reinspection?					Ye	S					
Remedial Action																			

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/04/28
Inspector in Charge's Name Richard David	Inspection Team N/A	