



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD 2022/05/02	Report Number	
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	WMATA	Contact Information	
Inspection Location	CM A1 880+00		

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity #	1	Inspection Subject				Activity Code						
Job Briefing Employee Name/Title	WMATA RWIC	Accompanied Inspector?	No	Out Brief Conducted	Yes	Time	10:00 AM	Outside Shift	No			
Related Reports	AWIS INSPECTION AT E10	Related CAPS / Findings			N/A							
Related Rules, SOPs, Standards, or Other	Ref	Rule or SOP	Standard			Other / Title			Checklist Reference			
	INSPECTIONS CERTIFICATION AND PROCEDURES FOR CERTIFIED LOCATIONS FOR AWIS											
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A	
	X							X				
Line(s) & Track Number	CM A1 880+00			Chain Marker and/or Station(s)			From		To			
							A1 880+00		A1 879+00			
Vehicles	Head Car Number		Number of Cars			Equipment						
Description	WMATA vehicle engineers and TRST personnel certified this location for an AWIS system that will help assist in reading 'back to back' measurements of railcars. This site is located adjacent to WMATA's TBS.							Number of Defects				
								Recommended Finding?			No	
								Remedial Action Required?			No	
								Recommended Reinspection?			No	
Remedial Action												



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Photos:

20220502_111100_lsb_210418_rsb_.jpg



20220502_102821_lsb_210419_rsb_.jpg





Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

20220502_110229_lsb_210422_rsb.jpg



¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/05/02
Inspector in Charge's Name JeMayne Walker	Inspection Team	