

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Report Number	
Inspection Date	2022/05/21	Report Number	
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	WMATA	Contact Information	
Inspection Location	E1 609+00		

Inspection Summary


Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	No


Activity Summaries

Inspection Activity #	1	Ins	pection Sub	ject	AWIS SYSTEM				Activity Code						
Job Briefing Employee Name/Title	WMATA RWIC			Accompanied Inspector?			No	Out Brief Conducted	Yes	Yes Time		01:00 AM		Outside Shift	Yes
Related Reports				Related CAPS / Findings					•	•			•		
Related Rules,	Ref		Rul	e or SOP			Standard		Other / Title Chec					ecklist Reference	
SOPs, Standards, or Other															
Inspection Location	Main Track	Yard	Station	occ	RTA F	acility	WMSC Office	Track Type	At-grade Tunne		el Elevated		N/A		
	Х								Х						
Line(s) & Track	E1 609+00				Chain Ma	rker and/	or Station(s)	From				То			
Number					Cilaiii iiia		o. o.a	E1 609+00							
Vehicles	Head Car Number			Number of Cars Equip			nent AWIS								
Verneies				Equipini			CIIC AWIS								
	WMATA contractors installed the first AWIS on the property to receive automated								Number of Defects						
Description	recordings of back to back measurements off railcars.									Recommended Finding?					lo
Description										Remedial Action Required?				No	
								Recommended Reinspection?					0		
Remedial Action															



Photos:














20220522_032115__lsb__213348__rsb__.jpg



20220522_032139__lsb__213346__rsb__.jpg





20220522 032807 lsb 213333 rsb .jpg














¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to analyze the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Actions.

Inspector in Charge's Signature	be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.	Date 2022/05/21
Inspector in Charge's Name JeMayne Walker	Inspection Team	