



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD 2023/03/17	Report Number	
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	TRST	Contact Information	
Inspection Location	A99 Shady Grove		

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	1
Recommended Finding	No
Remedial Action Required¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity #		Inspection Subject	Frog Replacement				Activity Code				
Job Briefing Employee Name/Title	N/A	Accompanied Inspector?	No	Out Brief Conducted	No	Time		Outside Shift	No		
Related Reports	None	Related CAPS / Findings			None						
Related Rules, SOPs, Standards, or Other	Ref	Rule or SOP			Standard		Other / Title		Checklist Reference		
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
		X									
Line(s) & Track Number	A99 Shady Grove				Chain Marker and/or Station(s)		From		To		
							N/A		N/A		
Vehicles	Head Car Number		Number of Cars			Equipment		N/A			
	N/A		N/A								
Description	WMSC personnel was at A99 yard to observe a cracked frog which caused single tracking on February 21st 2023. The #10 frog was located on the B Line at Fort Totten switch #7 on the track #2 (outbound). Due to the nature of the defect, track personnel had to replace it during revenue hours.							Number of Defects		1	
								Recommended Finding?		No	
								Remedial Action Required?		No	
								Recommended Reinspection?		No	
Remedial Action											



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Photos:

20230317_122922_lsb_255579_rsb_.jpg



20230317_123100_lsb_255572_rsb_.jpg



¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2023/03/17
Inspector in Charge's Name JeMayne Walker	Inspection Team N/A	